

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.
-

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
J. W. McInnis and H. N. Wood	A. E. Reeves
3. Address of Operator	9. Well No.
% Carl Engwall, P. O. Box 1782, Roswell, New Mexico 88201	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>F</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM	Eunice-Monument, G-SA
THE <u>West</u> LINE, SECTION <u>29</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3524' KB	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. In this report of Completed Operations, clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. SEE RULE 1103.

6-1-72 Well died and quit flowing
6-9-72 Cut paraffin in tubing, treat down tubing with 500 gal. Xylene plus 1500 gal. 15%
HAD acid with 1 gal. Adomell - Flush with 12 Bbl. water
6-9&10-72 Swab acid and load water and well resumed flowing.
Production prior to work over -0-, Production after work over 3 BOPD plus 100 MCFGPD
11-1-72 Well died and Quit flowing
12-9-72 Treat down tubing with 1000 gal. Paraclean WITH 2 gal. BD-11, flush with 39 Bbl.
lease crude - no response well dead.
1-8-73 Pulled tubing and packer
1-9&10-73 Ran tubing to 3821', ran down hole pump and rods.
1-11-73 Set pumping unit.
1-16-73 Completed electrical hookup and placed well into operation - on pump.
Production prior to work over -0-, Production after work over 7 BOPD plus 400 MCFGPD

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Carl Engwall TITLE Agent DATE March 1973

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: