

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
HOBBS OFFICE O.C.C.

DEC 12 3 37 PM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-4-65

5a. Indicate Type of Lease State <u>XIX</u> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <u>B-2441</u>
7. Unit Agreement Name
8. Farm or Lease Name <u>H. T. Orcutt (NCT-H) Com</u>
9. Well No. <u>2</u>
10. Field and Pool, or Wildcat <u>Paddock</u>
12. County <u>Lea</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator <u>Gulf Oil Corporation</u>
3. Address of Operator <u>Box 670, Hobbs, New Mexico</u>
4. Location of Well UNIT LETTER <u>C</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>1800</u> FEET FROM THE <u>West</u> LINE, SECTION <u>11</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <u>3608' OL</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Plugged and abandoned.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5736' PB, 6752' TD.

Pulled tubing to 5000'. Filled hole with 100 barrels of mud. Spotted 25 sack cement plug. Pulled tubing to 4500'. WOC 19 hours. Lowered tubing and found top of cement plug at 5070'. Pulled tubing and spotted 10 sack cement plug from 50' to surface. Squeezed 35 sacks cement in 8-5/8" - 5-1/2" casing annulus. Maximum pressure 1000#. Installed dry hole marker. Plugged and abandoned, December 12, 1966. (Location will be ready for inspection after December 16, 1966).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leshie V. Clement TITLE Area Production Manager DATE December 12, 1966

APPROVED BY Leshie V. Clement TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: