

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Keohane	
9. Well No. Blinebry	
10. Field and Pool, or Wildcat Weir Blinebry	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Dewey Sparger
3. Address of Operator Drawer 2158 Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER N , 660 FEET FROM THE South LINE AND 2310 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 20 S RANGE 38 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3567 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-28-75 Set one anchor rig up pulling unit, pull rods and pump, killed well with 35 bbls. lease oil and hot oil tubing, swab 33 bbls. back.
- 1-29-75 Pumping 200 gals N. E. acid 15% spotted with 20 bbl. lease oil let set 2 hours, swabbed acid load back, pumped 100 gals. clean # 420, spotted with 20 bbl. oil, run new pump and rods back in hole and started pumping.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dewey E. Sparger TITLE Operator DATE 1-31-75

APPROVED BY Joe D. Egan TITLE Dist. I. Secy. DATE

CONDITIONS OF APPROVAL, IF ANY: