

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. |
| 7. Unit Agreement Name |
| 8. Farm or Lease Name Keohane |
| 9. Well No. 3 |
| 10. Field and Pool, or Wildcat Weir Blinbry East |
| 12. County Lea |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| |
|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> |
| 2. Name of Operator Dewey E. Sparger |
| 3. Address of Operator Drawer 2158 Hobbs, N. M. 88240 |
| 4. Location of Well UNIT LETTER <u>K</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>1800</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>20S</u> RANGE <u>38E</u> NMPM. |
| 15. Elevation (Show whether DF, RT, GR, etc.) |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

| | |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> |

SUBSEQUENT REPORT OF:

| | |
|--|---|
| REMEDIAL WORK <input checked="" type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-2-75 Hot oiled down casing 40 bbls water, pulled rods.
5-5-75 Tried to run paraffin knife, tried to pump down casing with lease oil, couldn't pump down casing, put on blowout preventer, started pulling tubing, got out of hole with 23 joints, went back with overshot to fish for tubing, couldn't catch tubing.
5-6-75 Came out of hole and changed overshot, run overshot and 24 joints of tubing back and caught fish, pulled 24 joints and overshot out of hole, then swabbed tubing to 5000 ft. to empty tubing.
5-7-75 Came out of hole with 178 joints of tubing, run 1 joint back with cow plug 2' perforated sub. seating nipple one joint with tubing anchor then 204 joints 2 3/8 tubing, set anchor with 10 points.
5-8-75 Run pump and rods, replace well head and put to pumping.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| | | |
|---------------------------------|----------------------------------|-------------------------|
| SIGNED <u>Dewey E. Sparger</u> | TITLE <u>operator</u> | DATE <u>5-13-75</u> |
| APPROVED BY <u>[Signature]</u> | TITLE <u>SUPERVISOR DISTRICT</u> | DATE <u>MAY 16 1975</u> |
| CONDITIONS OF APPROVAL, IF ANY: | | |