UNITED STATES DEPARTMENT F THE INTERIOR

Porta approved, Budget Bureau No. 42 R1423. LEASE DESIGNATION AND SERIAL NO.

DEPARTMEN - 7 THE INTERIOR verse side) GEOLOGICAL SURVEY	5. LEASE DESIGNATION AND BERIAL NO. LC=045708 (b)		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR THISE NAME		
OIL X CAS OTHER	7. UNIT AGREEMENT NAME		
. NAME OF OPERATOR Imperial-American Management Co.	8. FARM OR LEASE NAME Parcell Federa!		
. ADDRESS OF OPERATOR 507 Midland Savings Bldg., Midland, Texas 79701	9. WELL NO.		
. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Undesigneted		
1980' FNL & 1980' FEL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AEFA		
	Sec. 19, 21-S, 38-E		
4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3497 GL	12. COUNTY OF PARISH 13. STATE Lea New Mexico		
6. Check Appropriate Box To Indicate Nature of Notice, Report, or G	Other Data		
NOTICE OF INTENTION TO:	UENT REPORT OF:		
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING (Other) (NOTE: Report result Completion or Recomp FRACTURE TREATMENT SHOOTING OR ACIDIZING (NOTE: Report result Completion or Recomp proposed work. If well is directionally drilled, give subsurface keations and measured and true vertice nent to this work.)*	REPAIRING WELL ALTERING CASING ABANDONMENT* Is of multiple completion on Well pletion Report and Log form.) 8, including estimated date of starting any cal depths for all markers and zones perti-		
Oue to failure to establish commercial production, this well has	been abandoned as follows:		
Rigged up GO International - set cast iron bridge plug	g @ 6650' w/20' cement on 1		
Rigged up 3onanza Casing Pullers. Loaded hole with mo 2780'. Pulled & laid down same.	ud. Shot off 7" casing		
Set 50 sx cement plug 2700-2800'. Set 50 sx cement plug 1500-1600'. Set 50 sx cement plug 825-925'. Set 10 sx cement plug 0-20'.			

Location ready for inspection 12-36-71.

Welded plate on casing and set marker.

I hereby certify that the foregoing is trie and correct	TITLE	Agent	DATE	12-3-71
(This space for Federal or State office use)				
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE		- 1917 M	
		THAT I	Affu	
*See	Instructions	on Reverse Side		

RECEIVED

JAN 11 1/2

OIL CORSOLVANOU COMM.