

UNITED STATES
DEPARTMENT OF THE INTERIOR

FORM 10-101 (REV. 10-1-61)

Form approved
Budget Bureau No. 42-R1424
5. LEASE DESIGNATION AND SERIAL NO.
LC-043703 (b)

REPORTS ON WELLS

6. INDIAN, ALLOTTEE OR TRIBE NAME

7. NE AGREEMENT NAME

8. FARM OR LEASE NAME

Parcell Federal

9. WELL NO.

10. FIELD AND COGOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 19, 21-S, 30-S

12. COUNTY OR PARISH

Lea

13. STATE

West Virginia

Imported American Iron

532 Midland Savin

1930' Full

COMPLETION REPORT OF:

1. WELL NO.

2. FIELD AND COGOL

3. SEC., T., R., M., OR BLK.

4. SURVEY

5. REPAIRING WELL

6. ALTERING CASING

7. ABANDONMENT

8. Name of person or company completing well (include completion of well, including estimated date of starting and completion, and include depth for all markers and zones pertinent to completion of well.)

No completion or alteration of well has been made. Therefore, no completion or alteration of well has been made.

I. Casing is as follows:

Surface casing - 8-5/8" x 26 ft. set at 12' x 1/2" cement

Production casing - 7-1/8" x 26 ft. set at 12' x 1/2" cement

II. Perforations as follows:

At 7'12" - 7'47" depth, 4" x 1/2" hole from bridge plug to 7'12" depth.

Drillard 7'75" - 7'107" depth, 4" x 1/2" hole.

Drillard 7'62" - 7'71" depth.

III. Proposed Abandonment as follows:

1. Load 10' x 1/2" cement.

2. Set cast iron bridge plug at 10' x 1/2" cement.

3. Shear off 2' of cement plug at 10' x 1/2" cement.

4. Set 100' cement plug at 10' x 1/2" cement.

5. Set 100' cement plug at 10' x 1/2" cement.

6. Set 50' x cement plug at 10' x 1/2" cement.

7. Set 10' x cement plug at 10' x 1/2" cement.

8. Cut off wellhead, install surface marker, clean up location.

3-17-71

APPROVED

DATE

For the Director