

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Hanson Oil Corporation		8. Farm or Lease Name Mattern	
3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88201		9. Well No. 1	
4. Location of Well UNIT LETTER <u>L</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>21-S</u> RANGE <u>37-E</u> NMPM.		10. Field and Pool, or Wildcat Blinebry	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is planned to re-treat Blinebry perforations 5516-5518 as follows:

1. Sand-water frac all perforations with 90,000 gals. gelled brine water, 120,000# 20-40 sand, 2000 gals. 15% acid.
2. Swab test.
3. Put well back on pump.

Approximate date work will commence: March 1, 1972

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gerald E. Harrington TITLE Geologist DATE 2-25-72

**Only Signed by**  
**John Ryan**  
**Geologist**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUL 22 1972

CONDITIONS OF APPROVAL, IF ANY: