

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-23507
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State "A" A/C 2
8. Well No. 61
9. Pool name or Wildcat Eunice SR Ou South
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR: 3584'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator CLAYTON W. WILLIAMS, JR., INC.
3. Address of Operator 6 Desta Drive, Suite 3000, Midland, TX 79705	4. Well Location Unit Letter J : 1980 Feet From The S Line and 1780 Feet From The F Line Section 8 Township 22S Range 36E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR: 3584'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work will commence upon OCD approval.

- 1) Set CIBP @ ±3750' and dump 35' of cement on CIBP.
- 2) Circulate the hole from CIBP to surface with 10 ppg gelled brine.
- 3) Spot balanced cement plugs from 300' - 450' (15 sx. Class "C") and from 3' - 150' (15 sx. Cl. C)
- 4) Cut the 4-1/2" and 7-5/8" csg. 3' below G.L. Set P&A marker. Cut deadmen. Clear location of all junk. Plug and abandon wellbore.

(See attached wellbore diagram)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David G. Grafe TITLE Petroleum Engineer DATE Feb. 23, 1993
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAR 19 1993

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: