

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Wtr. Injection		7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Co.		8. Farm or Lease Name State A A/C-2
3. Address of Operator P. O. Box 1861, Midland, TX 79702		9. Well No. 61
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1780</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>225</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat So. Eunice Seven Rvrs Qu
15. Elevation (Show whether DF, RT, GR, etc.) 3606 KB		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. NU BOP. Rise Baker AD pkr @ 3754'.
POH w/pkr & tbq. Visually inspect tubing.
2. RIH w/4 1/2 RBP & 4 1/2" FB pkr on 2 3/8 tbq.
3. Set RBP @ 3780'. Set pkr @ 3750' + & test RBP.
4. Locate csg leak by moving pkr. Isolate csg leak & EIR.
DUMP 1 SK sand on RBP. Sqz leak per Midland & instruction.
Rev. out, PU & WOC. Drill out cmt using 3 7/8 bit & 4--3 1/8 DC's on
2 3/8 tbq. Test sqz to 500 PSI, swab test. Re-sqz. if necessary. POH.

THE FOLLOWING IS A
TRUE AND CORRECT
COPY OF THE ORIGINAL
FILED IN THE
OFFICE OF THE
COMMISSIONER OF
ENERGY AND MINERALS
STATE OF NEW MEXICO
AT SANTA FE, NEW MEXICO
ON SEP 5 1985

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Velma Reyes

TITLE Sr. Accounting Asst.

DATE 9/3/85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

SEP - 5 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP - 4 1985

O.C.D.
HOBBS OFFICE