

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
NM 2A

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL CO., INC.	8. Farm or Lease Name State "A" A/c-2
3. Address of Operator P.O. Box 1069 - Hobbs, New Mexico 88240	9. Well No. 61
4. Location of Well UNIT LETTER J , 1980 FEET FROM THE South LINE AND 1780 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 22-8 RANGE 36-E NMPM.	10. Field and Pool, or Wildcat <i>No. Lease</i>
15. Elevation (Show whether DF, RT, GR, etc.) 3584.4' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Completion

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in, rig up. Run GR/N log.
2. Perf. with 1/2" jet charge @ 3793-3800-02-08-13-19-21-33-43-45-47-50-59-61-66-74-76'.
3. Ran 2-3/8" tbg. on treating pkr. and wash perfs. w/300 gal. mud acid.
4. Swabbed back mud acid. Set pkr. @ 3744' and acidized w/2000 gal. 15% NE acid.
5. Swabbed back load and tested.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED Sheldon Ward TITLE Area Supt. DATE 7-28-70

APPROVED BY [Signature] TITLE [Signature] DATE JUL 30 1970

CONDITIONS OF APPROVAL, IF ANY: