

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator HANSON OPERATING COMPANY, INC.		8. Farm or Lease Name MATTERN	
3. Address of Operator P. O. BOX 1515, ROSWELL, NEW MEXICO 88202-1515		9. Well No. 2	
4. Location of Well UNIT LETTER <u>K</u> , <u>198</u> FEET FROM THE <u>South</u> LINE AND <u>1783</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat BLINEBRY	
15. Elevation (Show whether DF, RT, GR, etc.) 3511 K.B.		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/3/85 Spotted 750 gal Gypsol over Blinebry perforations. Let set 24 hours, then acidized with 2500 gallons 15% NE Acid. Put well back on production May 4, 1985.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED David Sweeney TITLE Drilling & Production Super. DATE May 10, 1985

APPROVED BY DISTRICT SUPERVISOR TITLE  DATE MAY 10 1985

CONDITIONS OF APPROVAL, IF ANY: