	HORRENNEH, INMAND, DODIA	Budget Bureau No. 42-R1424
	HOBBEINTEUNSTATES 88240	5. LEASE
	DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	LC-030132(b)
		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		
1. oil well	gas well other Convert to SWD	8. FARM OR LEASE NAME Cities Federal
2. NAME C Zia	F OPERATOR a Energy, Inc.	9. WELL NO. 1 10. FIELD OR WILDCAT NAME
3. ADDRES	S OF OPERATOR D. Box 2219, Hobbs, NM 88240	Jalmat- 11. SEC., T., R., M. OR BLK. AND SURVEY OR
<ol> <li>LOCATIO below.)</li> </ol>	N OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 20-T22S-R36E
AT SURF AT TOP AT TOTA	FACE: PROD. INTERVAL: L DEPTH: 2310' FSL & 330' FWL	12. COUNTY OR PARISH 13. STATE
16. CHECK	APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, OR OTHER DATA	
	OR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3570' GR
TEST WATER	SHUT-OFF	and the second sec
SHOOT OR A		
PULL OR AL MULTIPLE C	OMPLETE	(NOTE: Report results of multiple completion of zone change on Form 9–330.)
CHANGE ZOI ABANDON*		
(other) C	convert to SWD	
measure It is	BE PROPOSED OR COMPLETED OPERATIONS (Clearly states gestimated date of starting any proposed work. If well is of d and true vertical depths for all markers and zones pertine proposed to squeeze off all Yate	arectionally drilled, give subsurface locations and int to this work.)*
get an and pr 3650' ture t	adequate squeeze pressure. Dri essure test. Drill out to total to 3800' in zones of porosity an creat as necessary to obtain adeq	cement or more if necessary to 11 out through these perforation depth of 3800'. Perforate from d stimulate with acid or frac- uate injection rate.
get an and pr 3650' ture t The in corros approx be fil instal The we dispos	e adequate squeeze pressure. Dri essure test. Drill out to total to 3800' in zones of porosity an	cement or more if necessary to ll out through these perforation depth of 3800'. Perforate from d stimulate with acid or frac- uate injection rate. bing with a PVC liner for D-1 packer will be set at yeen the tubing and casing will luid. A pressure gauge will be for tubing or packer leaks.
get an and pr 3650' ture t The in corros approx be fil instal The we dispos Subsurfaces	adequate squeeze pressure. Dri ressure test. Drill out to total to 3800' in zones of porosity an areat as necessary to obtain adeq spection string will be 2 3/8" tu tion protection. A Baker model A simately 3600'. The annulus betw led with a corrosion inhibited f led at the well head to monitor 11 will then be connected up and al well. afety Valve: Manu. and Type <u>None</u>	cement or more if necessary to ll out through these perforation depth of 3800'. Perforate from d stimulate with acid or frac- uate injection rate. bing with a PVC liner for D-1 packer will be set at yeen the tubing and casing will luid. A pressure gauge will be for tubing or packer leaks. placed in service as a water Set @Ft.
get an and pr 3650' ture t The in corros approx be fil instal The we dispos Subsurface S 18. Thereby	adequate squeeze pressure. Dri ressure test. Drill out to total to 3800' in zones of porosity an areat as necessary to obtain adeq spection string will be 2 3/8" tu tion protection. A Baker model A simately 3600'. The annulus betw led with a corrosion inhibited f led at the well head to monitor 11 will then be connected up and al well. afety Valve: Manu. and Type <u>None</u>	cement or more if necessary to ll out through these perforation depth of 3800'. Perforate from d stimulate with acid or frac- uate injection rate. bing with a PVC liner for D-1 packer will be set at yeen the tubing and casing will luid. A pressure gauge will be for tubing or packer leaks. placed in service as a water 
get an and pr 3650' ture t The in corros approx be fil instal The we dispos Subsurfaces 18. Thereby SIGNED	adequate squeeze pressure. Dri ressure test. Drill out to total to 3800' in zones of porosity an areat as necessary to obtain adeq spection string will be 2 3/8" tu ion protection. A Baker model A timately 3600'. The annulus betw led with a corrosion inhibited f led at the well head to monitor led at the well head to monitor led at the well head to monitor certify that the foregoing is true and correct performance. (This space for Federal or State off	cement or more if necessary to ll out through these perforation depth of 3800'. Perforate from d stimulate with acid or frac- uate injection rate. bing with a PVC liner for D-1 packer will be set at yeen the tubing and casing will luid. A pressure gauge will be for tubing or packer leaks. placed in service as a water 

Here

RECEIVED APR 26 1984 HOUSE

.