

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator  
**Gulf Oil Corporation**

3. Address of Operator  
**P. O. Box 670, Hobbs, NM 88240**

4. Location of Well  
UNIT LETTER **D** **330** FEET FROM THE **North** LINE AND **330** FEET FROM  
THE **West** LINE, SECTION **31** TOWNSHIP **21S** RANGE **37E** RMPM.

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

6. Farm or Lease Name  
**H. T. Mattern (NCT-B)**

9. Well No.  
**16**

10. Field and Pool, or Wildcat  
**Blinebry & Drinkard**

12. County  
**Lea**

15. Elevation (Show whether DF, RT, GR, etc.)  
**3511' GL**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO:                        |                                                             | SUBSEQUENT REPORT OF:                                |                                               |
|------------------------------------------------|-------------------------------------------------------------|------------------------------------------------------|-----------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/>        | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                       | COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/> <b>Abandon Blinebry zone</b> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> |                                               |
|                                                |                                                             | OTHER <input type="checkbox"/>                       |                                               |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

6766' PB. Set at RBP at 5760' and cap with 20' frac sand. Spot a 50 sack Class C cement plug at 5731'. Load hole with 8.6# kill fluid. Squeeze Blinebry perms 5532-5731' with Class C cement. WOC. Circ and clean out hole. Return Drinkard zone to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **A. P. Sikes, Jr.** TITLE **Area Engineer** DATE **5-8-78**

ORIG. SIGNED BY **Jerry Sexton** TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY **Dist 1, Supv.**

RECEIVED

1957 - 81972

DO CONSERVATION COMM.  
SUNDS, N. M.