NO. OF COPIES RECEIVED			N 55	rm C-101	
DISTRIBUTION				vised 1-1-65	
SANTAFE			5	A. Indicate Type of L	euse
FILE A				STATE	PER 🕅
U.S.G.S.			. 5	, State Oil & Gas Leo	180 No.
LAND OFFICE					
OPERATOR			5	inninnin i	
	DEFOCIU	OD DUUC BACK	(		
APPLICATION FOR PE	RMIT TO DRILL, DEEPEN,	UR PLUG DACK		7. Unit Agreement Nar	ne
1s. Type of Work			_		
	DEEPEN 🔀	PLUG	BACK	Farm or Lease Nam	
b. Type of Well			LTIPLE	H. T. Matterr	n (NCT-B)
OIL X GAS WELL OTH	IER	SINGLE MU		9. Well No.	
2. Name of Operator				16	
Gulf Oil Corporation				10. Field and Pool, or	r Wildcat
3. Address of Operator				Drinkard	
Box 670, Hobbs, N.M. 882	40		<del>k</del>	<u>minnin</u>	mmm
4. Location of Well UNIT LETTER D	LOCATED	FEET FROM THE NOT	LINE LINE		
		TWP 21S RGE	37E NMPM		HHHHH
AND 330 FEET FROM THE WI	est LINE OF SEC. 31	TWP. 21.5 RGE.		12. County	*****
				Lea	
		<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	+++++++++++++++++++++++++++++++++++++++	hmmm	HHHHH
$\qquad \qquad $					
			19A. Formation	20. Rote	my or C.T.
<i></i>		19. Proposed Depth			
		68].0*	Drinkar	22. Approx. Date W	rse Unit
21. Elevations (Show whether DF, RT, etc.)	21A. Kind & Status Plug. Bond	21B. Drilling Contractor		10-14-75	JIR WILL DUAL
3511 ° GL	Blanket			10.14 12	
23		ND CENENT BROCKAM			

PROPOSED CASING AND CEMENT PROGRAM

		SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
				1237	400 sx	<u>urcuraceu</u>
11. 735 sx 100	11"		71 8. 717#		735 sx	TOC at 2080
$7-7/811$ $5-1/2.11$ $14 \le 1/11$	7-7/8"	) <b>-</b> 1/2"	14 0 1.111			

Deepen and complete in Drinkard as follows: Squeeze Blinebry perforations 5532-5731° with 100 sacks Cement. WOC 24 hours. Test squeezed Blinebry perforations with 500# 30 minute. Drill 4-3/4" hole to approximately 6810". Set 4" OD 11.34# K-55 Hydrill FJ liner at 6810 with top at 5770 . Cement with approximately 150 sacks cement. WOC 24 hours. Clean out and test liner with 4000% for 30 minutes. Perforate Drinkard zone in 4" liner with 4,  $\frac{1}{2}$ " JHPF in the interval 6475" to 6750". Run treating equipment and treat new perforations with 2000 gallons 15% NE acid and frac treat with 30,000 gallons gel water containing 1 to 2# SPG. Flush with 42 barrels of gel water. Pull treating equipment. Run packer and 2-3/3" tubing. Set packer at approximately 5795". Swab and clean up and place well on production.

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM! IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUC-TIVE ZONE, GIVE BLOWOUT PREVENTER PROGRAM, IF ANY. to the best of my knowledge and belief.

	377121.31	Tule_Area Engineer	Date <u>11-10-75</u>
	ce for State Use)		NOVIE
ADDDAVED BY		TITLE	DATE

CONDITIONS OF APPROVAL, IF ANYI

