'orrn 3160-5 June 1990)	DEPAR I MENT (ED STATES DF THE INTERIOR ND MANAGEMENT	N.M. Oil Co	Expire	s: March 31, 1993
S	UNDRY NOTICES AND	REPORTS ON WELL	Hobbs, NM 88241		nation and Serial No.
				NM-6	
Do not use this form for proposals to drill or deepen or reentry to a different reservior. Use "APPLICATION FOR PERMIT-" for such proposals				ottee or Tribe Name	
				N/A	
SUBMIT IN TRIPLICATE					, Agreement Designation
	as Other			ARRO 8. Well Name a	WHEAD GRAYBURG UNIT
. Name of Operator		······································			161
CHEVRON U.S.A. INC.				9. API Well No	
Address and Telephone No.				30-02	5-24528
P. O. Box 1150, Midland, TX 79702 (915)687-7148				10. Field and P	ool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL & 660' FEL					WHEAD;GRAYBURG
SEC. 1,T22S,R36	· ·	NIT H		11. County or F	Parish, State
				LEA, N	INA
CHE	CK APPROPRIATE BOX	(S) TO INDICATE N	ATURE OF NOTICE, REPO	DRT, OR OTH	IER DATA
	BIVIISSION		TYPE OF ACTION		
XX No	ptice of Intent	Ab	pandonment	Change of	f Plans
~ ~	the environment Decision	Re	completion	New Cons	struction
	ibsequent Report		ugging Back	Non-Routi	ne Fracturing
	al Abandonment Notice		sing Repair	Water Shu	ıt-Off
L L Lio		i Alte	ering Casing	Conversio	n to Injection
Fin			· ·		
Decribe Proposed or Completed Ope give subsurface locations and mer RAN CASING INT	erations (Clearly state all pertinent deta asured and true vertical depths for all m EGRITY TEST 4/10/98	Is, and give pertinent dates, includ arkers and zones pertinent to this WELL WILL BE TA	her ding estimate date of starting any proposed work.)*	Dispose V (Note: Report results o Completion or Recomp work. If well is directi	f multiple completion on Weil Jetion Report and Log form.) onally drilled.
Decribe Proposed or Completed Op give subsurface locations and mer RAN CASING INT	erations (Clearly state all pertinent deta asured and true vertical depths for all m EGRITY TEST 4/10/98	Is, and give pertinent dates, includ arkers and zones pertinent to this WELL WILL BE TA	her ding estimate date of starting any proposed work.)*	Dispose V (Note: Report results o Completion or Recomp work. If well is directi	f multiple completion on Weil Jetion Report and Log form.) onally drilled.
Decribe Proposed or Completed Ope give subsurface locations and mer RAN CASING INT	erations (Clearly state all pertinent deta asured and true vertical depths for all m EGRITY TEST 4/10/98	Is, and give pertinent dates, includ arkers and zones pertinent to this WELL WILL BE TA ', DUMP 35' CMT C	her ding estimate date of starting any proposed work.)* A'D AS FOLLOWS: DN TOP. TEST 500# FOR	Dispose V (Note: Report results o Completion or Recomp work. If well is directi	f multiple completion on Well Jetion Report and Log form.) onally drilled.
Decribe Proposed or Completed Opi give subsurface locations and mer RAN CASING INT POH W/PROD EQ POH W/PROD EQ	erations (Clearly state all pertinent deta asured and true vertical depths for all m EGRITY TEST 4/10/98. PT. SET CIBP @ 3590	LS. and give pertinent dates, includ arkers and zones pertinent to this WELL WILL BE TA ', DUMP 35' CMT C CONDISION	her ding estimate date of starting any proposed work.)* A'D AS FOLLOWS: DN TOP. TEST 500# FOR	Dispose V (Note: Report results o Completion or Recomp work. If well is directi	f multiple completion on Well Jetion Report and Log form.) onally drilled.
Decribe Proposed or Completed Opi give subsurface locations and mer RAN CASING INT POH W/PROD EQ	erations (Clearly state all pertinent deta asured and true vertical depths for all m EGRITY TEST 4/10/98. PT. SET CIBP @ 3590	Is, and give pertinent dates, includ arkers and zones pertinent to this WELL WILL BE TA ', DUMP 35' CMT C CONDER ST	her ding estimate date of starting any proposed work.)* A'D AS FOLLOWS: DN TOP. TEST 500# FOR	Dispose V (Note: Report results o Completion or Recomp work. If well is directi 30 MINUTE	f multiple completion on Well Metion Report and Log form.) Onally drilled. S.

5