

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI. DATE
Other instruction in the
reverse side

RECEIVED

LEASE DESIGNATION AND SERIAL NO.
NM-062665
IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER Seal
2. NAME OF OPERATOR Conoco Inc.
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, NM 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

5. UNIT AGREEMENT NAME
6. FARM OR LEASE NAME Lockhart B-1
7. WELL NO. 9
8. FIELD AND POOL, OR WILDCAT Blindly O/G / Shunkard
9. SEC., T. R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T22S, R36E
10. COUNTY OR PARISH Lea 11. STATE NM

Unit-I 1980' FSL + 660' FEL

14. PERMIT NO. 30-025-24529
15. ELEVATIONS (Show whether OF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) Repair 8 5/8" csg. part ☒
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8 5/8" csg. collapsed 5' below wellhead. NDWH, NUBOP. Kill well
POH w/ tbg. 6 1/4" w/ RBP, set @ 5000' Test to 500# held. Dig out cellar
to 8 5/8" csg. part. 6 1/4" w/ 5 1/2" RBP set @ 300', test to 500#, held.
Cut off 5 1/2" & 8 5/8" wellhead. Cut off 8 5/8" csg. 9' below
ground level. Install new csg. & 8 5/8" wellhead. Install
5 1/2" csg. head. Release RBP @ 300'. POH. 6 1/4" w/ 2 7/8" tbg.
Release RBP @ 5000'. Run prod. equip. Return to prod.

18. I hereby certify that the foregoing is true and correct

SIGNED H.A. Ingram TITLE Conservation Coordinator DATE 4/4/90
(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side