

DISTRICT I

P. O. Box 1980, Hobbs, NM 88240

DISTRICT II

P. O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 87504-2088

WELL API NO.

30-025-24568

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

B-2148

7. Lease Name or Unit Agreement Name

Downes "D"

8. Well No.

4

9. Pool name or Wildcat

Blinbery/Tubb

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1 Type of Well:

OIL

WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

The Wiser Oil Company

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797

4. Well Location

Unit Letter M : 660 Feet From The South Line and 810 Feet From The West Line

Section 32 Township 21S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3464' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

OTHER: Acidize Tubb and comingle downhole

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 5/17/01 MIRU Tyler Well Service. Pump 100 bbls. 2% KCL down csg. POH w/pump & rods. NU BOP. RIH w/tbg. Tag @ 5812'. POH w/tbg.
5/18/01 RIH w/bulldog bailer on 2-7/8" tbg. to 5812'. Clean out to 5850'. POH w/tbg. & bailer. Sand bridged in 2-7/8" cavity. RIH w/bailer. Tag @ 5840'.
POH w/2-7/8" tbg. & bailer.
5/15/01 TIH w/2-7/8" tbg. & bailer. Tag @ 5840'. Clean out sand & ball sealers to 5980'. POH w/tbg. & bailer. Clean out 2-7/8" cavity & bit. RIH w/bit, 2-
7/8" tbg. & bailer. Clean out to 6000' & CIBP. Drill on CIBP.
5/23/01 Tag fill @ 5970'. Clean out fill to CIBP. Drilling on CIBP. POH to 5500'.
5/24/01 TIH w/2-7/8" tbg., bailer & bit. Tag CIBP @ 6000'. Knock plug to 6236'. Pump 100 bbls. 2% KCL. Tag plug @ 6236'. POH w/2-7/8" tbg., bailer &
bit. MIRU Computalog WL & perforate Tubb f/6161'-63',65'-66',6171'-72',75'-79',6181',83',85'-86',88',6190',97',99',6200',02',21',23'-25',27'-29'
& 31' w/4 SPF. RD WL.
5/25/01 Pump 55 bbls. produced water down csg. MIRU Cudd Pressure Service & pump brine water down csg. RIH w/pkr., SN & 2-7/8" tbg. Set pkr. @ 6094'.
Acidized Tubb w/3500 gals. 15% NE-FE acid w/3000# rock salt. ISIP 1200#. 5 min. 800#. 10 min. 700#. 15 min. 600#. Max.
Pressure 4200#. Min. Pressure 1400#. Avg. Pressure 1800#. RD Cudd.
5/29/01 Release pkr. & pull 4 stands. Pkr. hung up. Work pkr. loose & POH w/2-7/8" tbg. Left pkr. in hole. RIH w/4 11/16" overshot w/2" grapple. Tag pkr.
@ 6094'. Push pkr. to 6248'. POH w/overshot & pkr. RIH w/2-7/8" tbg. SN @ 6100'.
5/30/01 RD BOP. NU WH. RIH w/rods & 2-1/2" x 1-3/4" x 20' pump. Pressure test tbg. to 500#. Left well pumping to Battery. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II

DATE October 8, 2001

TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY

TITLE LAUREN E. KAUTZ
PETROLEUM ENGINEER

DATE JAN 11 2002