

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instruction
reverse side)

DATE
0 10

LEASE DESIGNATION AND SERIAL NO.
NM-013126

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Meyer B-23
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, NM 88240	9. WELL NO. #5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 660' FEL Unit P	10. FIELD AND POOL, OR WILDCAT Eunice 7 Rms. Queen So.
14. PERMIT NO. 30-025-2486	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23, T-22S, R-36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3491' DF	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Notify BLM before beginning operation.
Set CIBP @ 3690'. Load & circ. well w/85 bbls. mud.
Pump 25 sk cement and displace w/20 bbls mud to spot plug on CIBP from 3443' to 3690'. Load hole w/4 bbls mud.
Pump 11 sk cement and displace w/9 bbls mud to spot plug from 1541' to 1650'. Perf. 5 1/2" prod. csg. @ 550'. Pump 36 bbls mud to load hole and establish circ. Pump 160 sk cement to fill 8-5/8" x 5-1/2" annulus and set surface plug. Prepare surface location for abandonment.

18. I hereby certify that the foregoing is true and correct

SIGNED

W.W. Baker

TITLE

Administrative Supervisor

DATE

1-4-90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

1-10-90

*See Instructions on Reverse Side