

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM 0557686

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SEMU Skaggs B

8. Well Name and No

Well #95

9. API Well No.

30-025-249J8

10. Field and Pool, or Exploratory Area

11. County or Parish, State

Lea, N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other **Disposal**

2. Name of Operator

Conoco, Inc.

3. Address and Telephone No.

10 Desta Drive Ste. 100W, Midland, Tx. 79705-4500 (915) 686-5580/684-6381

4. Location of Well (Footage, Sec., T. R. M. or Survey Description)

**2130' FSL & 1980' FEL
Sec 23, T20S, R37E, J**

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☒ Altering Casing **tubing/fish**
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-3-99: MIRU, NDWH, NUBOP, RIH w/overshot & tbg, didn't tag fish, RIH didn't tag, ran 1281' of tbg. SION.
5-4-99: Open up well, POOH w/40 jts overshot, rack 166 jts, tally tubing, SION.
5-5-99: Open up well, RIH w/overshot picking up tubing, tag @ 3834', wouldn't go down, POOH change overshot, RIH tag @ 3834', work w/tool, wouldn't go down, SION.
5-6-99: Finish POOH w/overshot, RIH w/8 5/8" scrapper, POOH run overshot, latch onto fish, pulled 4 jts, couldn't move up or down, work w/fish installed 8 5/8" BOP. SION.
5-7-99: Open up well, worked w/tbg, wouldn't come free, tried to back off, SION.
5-10-99: RU wireline, freepoint - stuck @ 4576', pkr @ 4576', shot tbg off @ 4575', RD wireline, POOH laying down tbg, SION.
5-11-99: Open up well, RIH w/8 5/8" scrapper tag liner top @ 3805', circulate hole, POOH w/scrapper, RIH w/ 4 3/4" shoe w/tbg, pulled 28 jts, SION.
5-12-99: Open up well, ran 28 jts tag @ 4570', RU swivel, circulate to 4576', pkr went down hole to 4592, cut on pkr, circulate clean, pull 30 jts, SION.
5-13-99: Open up well, ran 30 jts, milled on pkr, pushed down to 4604', POOH RIH w/new shoe. SION.
5-14-99: RIH w/30 jts, drilled to 4601', POOH, SION. 5-15-99: Milled on pkr, POOH, didn't have pkr. SION.
5-17-99: RIH w/shoe, tag @ 4606', drill to 4607', pulled 28 jts, SION. 5-19-99: Drilled to 4734', lost circulation, SION.
5-20-99: Open up well, RIH w/2 3/8" to 4737', pumped 500 gals 15% acid, RIH w/pkr, SN, testing. SION.
5-21-99: Set pkr, NUWH, load csg, w/pkr fluid, pressure test to 500#, held. Pulled 145 jts. 2 3/8", ran 4582' plastic coated 2 3/8".

14. I hereby certify that the foregoing is true and correct.

Signed

Title

**Ann E. Ritchie
Regulatory Agent**

Date

July, 5, 1999

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval if any:

BLM(6)

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

JCS GWW