

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instruction
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC-0634580
2. NAME OF OPERATOR Conoco Inc		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs NM 88240		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FWL Unit Letter C		8. FARM OR LEASE NAME Warren Unit
14. PERMIT NO. 30-025-25058		9. WELL NO. 34
15. ELEVATIONS (Show whether DF, RT, CR, etc.) ?		10. FIELD AND POOL OR WILDCAT NMFIL / Blinney Oil & Gas
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 34-20S-38E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Repairate & Acidize	
(Other)		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Spot 29 bbls 15% HCL-NE-FE acid from 6650'-6300' & 6200'-5800'. Perf Blinney at 5816'-5888' w/1 3SPF. Perf Tubb on 2nd trip at 6386'-6650'. Set RBP at 6450' & test to 3000 psi. Set pkr at 6256'. Acidize Upper Tubb perms 6386'-6393' w/30 bbls 15% HCL-NE-FE acid. Drop 2 ballsealers every 5 bbl acid pmpd. Flush w/41 BTFW. Swab well. Release pkr & RBP. Set RBP at 6720' & pkr at 5716'. Acidize Blinney & Tubb perms 5814'-5888' & 6386'-6650' w/64 bbls 15% HCL-NE-FE acid w/85 gals checker sol. Dropped 4 ballsealers every 4 bbl acid pmpd. Flush w/69 BTFW. Release RBP & pkr. Land anchor at 5663' w/12 pts tension. SN at 6620'. Run pump & rods.

18. I hereby certify that the foregoing is true and correct

SIGNED Jim Kull TITLE Administrative Supervisor DATE July 28, 1987

(Leave space for Federal or State office use)

APPROVAL OF
COMMISSIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD
DATE

AUG 7 1987

*See instructions on Reverse Side

SJS

CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) ARCO (2) Amoco (2) Chevron (1) Zil.

RECEIVED

AUG 10 1987

OCD
HOBBS OFFICE