

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC		8. FARM OR LEASE NAME Warren Unit
3. ADDRESS OF OPERATOR P.O. Box 460, Hobbs, N.M. 88240		9. WELL NO. 34
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit C		10. FIELD AND POOL, OR WILDCAT Blindburg / Subb Warren
14. PERMIT NO. 30-025-25058		11. SEC., T., R., EA, OR BLK. AND SURVEY OR AREA Sec. 34, T20S, R38E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 660' JNW + 1980' JWB		12. COUNTY OR PARISH LEA
		13. STATE NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANE <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other: Reperforate + Acidize)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. M2L RU. POOH w/rods + pump. GIH w/csg scraper + bit to 6850'. Spot Acid, 15% HCl-NE-FE, from 6650'-6300' + 6200'-5800'. Perf. Blindburg w/1 JSPF @ 5816', 44', 76', 84', 88'. Perf Subb w/1 JSPF @ 6386', 88', 90', 91', 92', 93', 6541', 46', 62', 69', 6601', 22', 29', 48', 6650'.

2. Set RBP @ 6450', set packer @ 6270'.

3. Acidize upper Subb perfor w/12 bbls 15% HCl-FE w/25 gal Checkw sol. Release packer + RBP.

4. Set RBP at 6720', set packer @ 5710'. Acidize all perfor w/64 bbls 15% HCl-FE, rel. packer + RBP. POOH. GIH w/production equipment + turn well to test system.

18. I hereby certify that the foregoing is true and correct

SIGNED William Charles DE FINEY TITLE Administrative Supervisor DATE February 27, 1987

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE _____ DATE 3-16-87

CONDITIONS OF APPROVAL, IF ANY: _____

*See instructions on Reverse Side

Title 18 U.S.C. Section 1001 makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) AR00 (2) Conoco (2) Chevron (1) File