Form 9-331 Form Approved. Dec. 1973 Budget Bureau No. 42-R1424 UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR LC-063458 **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS WARREN (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 8. FARM OR LEASE NAME WARREN LINIT gas well 📝 well other 9. WELL NO. 48 2. NAME OF OPERATOR 10. FIELD OR WILDCAT NAME CONTINENTAL 3. ADDRESS OF OPERATOR WARREN BLINEBRY - TUBB 11. SEC., T., R., M., OR BLK. AND SURVEY OR HOBBS . X. M. 88240 4/60 **AREA** 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 SEC. 26, T-205, R-38E AT SURFACE: 2030' FNL 1980' FWL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: LBA <u>N. M.</u> AT TOTAL DEPTH: 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE! Report results of multiple completion or zone PULL OR ALTER CASING change (on Form 1943789.) MULTIPLE COMPLETE CHANGE ZONES U. S. GEOLOGICAL SURVEY

WAR NORCE

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

HOBBS, NEW MEXICO

DRILLED 874 "HOLE TO 7070' T.D. RAN 7", 23th CAEING TO 7065' KB.

D.V. TOOL SET @ 3989'

CEMBITED FIRSTSTAGE WIJ 550 SX CLASS "L" CEMBRIT W/ Additives. Drappe

PLUG and displaced to gloat collar WI 125 bb/s TPW \$ 151 bb/s day must

Bump plug & T: 40 pm. Open DV. tool & 8:20 pm. Circul. FOR 4 HRS.

Cembrited Second STAGE W/ 1875 SX Howco LITE-WATE CEMBRIT W/ AUDITIVES.

DROP PLUG : Disp TO DV. TOOL W/ 157 bb/s TFW. Bump plug i close D.V. TOOL

O 2:20 Am. Circulate 100 SX CMT TO SURFACE. REL. RIG. 7-27-78.

DROP PLUG : DISP TO DV. TOOL W/ 157 661	
@ 2:20 Am. CIRCULATE 100 SX CMT TO S	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED WM. Q. Phillippiel TITLE ADMINISTRATIVE	
(This space for Federal or State	office use Accepted for Record
APPROVED BY	AUG 2 1978
*See Instructions on Revers	U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO

ABANDON*

(other) SET PRODUCTION