Lever if the Conton of

المراجعة المحمد . 1993 - محمد مراجع المراجع المراجعة المحمد مع محمد مع محمد مع المراجع . 1994 - مراجع المحمد مع محمد مع

n an amin'n Start anna 1997. Start ann an Start anna 1997. Start

	Budget Bureau No. 42-R1424
UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil 🖄 gas well 🖄 well 🗆 other	Gillully B Federal KATH
2. NAME OF OPERATOR	9. WELL NO.
Amoco Production Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Monument Paddock
P. 0. Box 68 Hobbs, NM 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below)	21-20-37
AT SURFACE: 660' FNL X 1650' FEL, Sec. 21 AT TOP PROD. INTERVAL: (Unit B, NW/4, NE/4) AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO.
	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3533' RDB
TEST WATER SHUT-OFF	
FRACTURE TREAT	
	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING TO SEP 11	4000 change on Form 0 220)
ABANDON* U. S. GEOLOG	BICAL SURVEY
(other) HO3BS, N	EW MEXICO
Moved in service unit 8-19-80. Ran 5-1/2" ce retainer at 5066'. Squeeze perforations 5130	ement retainer and tubing and set
<pre>cement with .3% Halad-3 and additives. Rever Pulled tubing. Ran 43/4" bit, drill collars retainer and cement to 5211'. Test perfs to casing gun and perforated Paddock intervals 5 and 5164'-68' with 2 DPJSPF. Ran packer, tub Spotted 72 gallons NEFE acid across perfs. S 1000 gallons 15% NEFE acid. Flushed with 30 radioactive material. Ran gamma ray log. Sw ran pumping equipment. Returned well to prod in 24 hr. was 83 BO and 555 BW. Subsurface Safety Valve: Manu. and Type</pre>	rsed out 55 sacks of cement. s, and tubing and drilled out 500# - O.K. Pulled bit and ran 5130'-34', 5137'-44', 5155'-61', oing, and tailpipe to 5180'. Set packer at 5036'. Acidized wit bbls. 2% KCL. All acid tagged wit vabbed load. Pulled packer and duction. Production after workove
 Pulled tubing. Ran 4-3/4" bit, drill collars retainer and cement to 5211'. Test perfs to casing gun and perforated Paddock intervals 5 and 5164'-68' with 2 DPJSPF. Ran packer, tub Spotted 72 gallons NEFE acid across perfs. S 1000 gallons 15% NEFE acid. Flushed with 30 radioactive material. Ran gamma ray log. Sw ran pumping equipment. Returned well to prod in 24 hr. was 83 BO and 555 BW. Subsurface Safety Valve: Manu. and Type	rsed out 55 sacks of cement. s, and tubing and drilled out 500# - O.K. Pulled bit and ran 5130'-34', 5137'-44', 5155'-61', oing, and tailpipe to 5180'. Set packer at 5036'. Acidized wit bbls. 2% KCL. All acid tagged with wabbed load. Pulled packer and duction. Production after workove Set @Ft.
 Pulled tubing. Ran 4-3/4" bit, drill collars retainer and cement to 5211'. Test perfs to casing gun and perforated Paddock intervals 5 and 5164'-68' with 2 DPJSPF. Ran packer, tub Spotted 72 gallons NEFE acid across perfs. S 1000 gallons 15% NEFE acid. Flushed with 30 radioactive material. Ran gamma ray log. Sw ran pumping equipment. Returned well to prod in 24 hr. was 83 BO and 555 BW. Subsurface Safety Valve: Manu. and Type	rsed out 55 sacks of cement. s, and tubing and drilled out 500# - O.K. Pulled bit and ran 5130'-34', 5137'-44', 5155'-61', oing, and tailpipe to 5180'. Set packer at 5036'. Acidized wit bbls. 2% KCL. All acid tagged with wabbed load. Pulled packer and duction. Production after workove
Pulled tubing. Ran 4-3/4" bit, drill collars retainer and cement to 5211'. Test perfs to casing gun and perforated Paddock intervals 5 and 5164'-68' with 2 DPJSPF. Ran packer, tub Spotted 72 gallons NEFE acid across perfs. S 1000 gallons 15% NEFE acid. Flushed with 30 radioactive material. Ran gamma ray log. Sw ran pumping equipment. Returned well to prod in 24 hr. was 83 BO and 555 BW. Subsurface Safety Valve: Manu. and Type 18. I hereby pertify that the Goregoing is true and correct SIGNED	rsed out 55 sacks of cement. s, and tubing and drilled out 500# - O.K. Pulled bit and ran 5130'-34', 5137'-44', 5155'-61', oing, and tailpipe to 5180'. Set packer at 5036'. Acidized with bbls. 2% KCL. All acid tagged with vabbed load. Pulled packer and duction. Production after workove <u>Set @</u> Ft. <u>Set @</u> Ft. <u>(st9-16-80</u>
 Pulled tubing. Ran 4-3/4" bit, drill collars retainer and cement to 5211'. Test perfs to casing gun and perforated Paddock intervals 5 and 5164'-68' with 2 DPJSPF. Ran packer, tub Spotted 72 gallons NEFE acid across perfs. S 1000 gallons 15% NEFE acid. Flushed with 30 radioactive material. Ran gamma ray log. Sw ran pumping equipment. Returned well to prod in 24 hr. was 83 BO and 555 BW. Subsurface Safety Valve: Manu. and Type	rsed out 55 sacks of cement. s, and tubing and drilled out 500# - O.K. Pulled bit and ran 5130'-34', 5137'-44', 5155'-61', oing, and tailpipe to 5180'. Set packer at 5036'. Acidized wit bbls. 2% KCL. All acid tagged with vabbed load. Pulled packer and duction. Production after workove