

COPY TO O. C. C.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR
Continental Oil Company

3. ADDRESS OF OPERATOR
P.O. Box 460 Jansen, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: *660' FNL & 1980' FNL*
AT TOP PROD. INTERVAL: *-*
AT TOTAL DEPTH: *-*

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	☐	☐
FRACTURE TREAT	☐	☐
SHOOT OR ACIDIZE	☐	☐
REPAIR WELL	☐	☐
PULL OR ALTER CASING	☐	☐
MULTIPLE COMPLETE	☐	☐
CHANGE ZONES	☐	☐
ABANDON*	☐	☐
(other) <i>set 7" prod. casg</i>	☒	☒

5. LEASE
82 063-58

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
7m 12

8. FARM OR LEASE NAME
Strawson Unit

9. WELL NO.
53

10. FIELD OR WILDCAT NAME
Blindley & Fuld

11. SEC., T., R., AND OR BLK. AND SURVEY OR AREA
Sec. 26, T-205, R-380

12. COUNTY OR PARISH
San

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3561.5' CR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-8-78 Hit TD 6825', ran logs, prep to run 7" casing

11-9-78 RUN FLOAT SHOE, 47' - 7" OD 26#, K-55, 8FD, LT&C SHOE JT, FLOAT COLLAR, 26 JTS 7" OD, 26#, K-55, 8FD, LT&C CSG, 41 JTS 7" OD, 23#, K-55, 8FD, LT&C CSG, DV TOOL & 100 JTS 7" OD, 23#, K-55, 8FD LT&C CSG. SET CSG AT 6825' KE, 6814' GL W/FLOAT COLLAR AT 6784' KE, 6773' GL & DV TOOL AT 4018' KE, 4007' GL. RI & CMT AS FOLLOWS: PUMP 5 BELS FW SPACER, 500 GALS MUD SWEEP, 5 BELS FW SPACER, 225 SKS LEAD CMT W/4% GEL & 3#/SK SALT. TAIL IN W/325 SKS CLASS "C" CMT W/3#/SK SALT. DISPLACE W/110 BELS TFW & 159 BELS FW. PLUG DOWN ON 1ST STAGE AT 1:00 PM, 11-9-78. DFOF FREE FALL PLUG, DV TOOL OPEN AT 1:30 PM, CIRC 4 HRS. PUMP 2ND STAGE - 1595 SKS EJ LITE CMT, 18% SALT. DISPLACE W/160 BELS TFW. PLUG DOWN AT 7:30 PM, 11-9-78. Subsurface S. RELEASE RIG AT 11:00 PM, 11-9-78.

18. I hereby certify that the foregoing is true and correct

SIGNED *Wm A. Balthasar* TITLE *Administrative Supervisor* DATE *11-10-78*

(This space for Federal or State official use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*USGS
NM & A
File*

ACCEPTED FOR RECORD
NOV 13 1978
U. S. GEOLOGICAL SURVEY
MORGAN, NEW MEXICO

*See Instructions on Form 9-330