

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enx Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25929

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Exxon Corporation Attn: Judy Bagwell

3. Address of Operator
P. O. Box 1600, Midland, TX 79702

7. Lease Name or Unit Agreement Name

F. F. Hardison B

8. Well No.
10

9. Pool name or Wildcat
Drinkard/Wantz Abo

4. Well Location
Unit Letter A : 990 Feet From The North Line and 450 Feet From The East Line
Section 34 Township 21S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3389 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-6-90 - RIH tbg and scraper. Hit CIBP at 6258'.
8-7-90 - Jerry Sexton, NMOC, required plug at 6258' to be drilled out.
Began drlg.
8-8-90 - Drilled out CIBP. Cleaned out to 7272', displaced hole with
produced water.
8-9-90 - Set CIBP at 6615', displaced w/salt gel mud. Pumped 10 sx C1 C cmt
on top, disp w/salt gel mud. Set plug at 6285-6085, disp w/salt
gel mud.
8-10-90 - Tag cement plug at 6384'. Pull up to 6363', pumped 50 sx C1 C
cement - 6363-6112, disp w/20 bbl salt gel flush.
8-11-90 - Tag cement plug at 6112', disp w/salt gel. 20 sx cement plug
4000 - 3900', disp w/salt gel. 20 sx cement plug 1250 - 1150',
disp w/salt gel. Circ cement 50' to surface. Weld on plate and
dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Judy Bagwell
Judy Bagwell
TYPE OR PRINT NAME

TITLE Sr Staff Office Asst
DATE 10-24-91
915/
TELEPHONE NO. 688-7546

(This space for State Use)

APPROVED BY

R. A. Salter

OIL & GAS INSPECTOR

TITLE

DATE

OCT 28 1991

CONDITIONS OF APPROVAL, IF ANY: