

State of New Mexico
Energy, Minerals & Natural Resources

Form C-101
Revised March 17, 1999

District I
625 N. French Dr., Hobbs, NM 88240
District II
111 S. 1st Street, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Submit to appropriate District Office
State Lease - 6 Copies
Fee Lease - 5 Copies

☐ AMENDED REPORT

APPLICATION FOR PERMIT TO DRILL, RE-ENTER, DEEPEN, PLUGBACK, OR ADD A ZONE

¹ Operator Name and Address Anadarko Petroleum Corp. P.O. Box 2497 Midland, TX 79702		² OGRID Number 000817
⁴ Property Code 1325		³ API Number 30- 30-025-26075
⁵ Property Name LANGLEY GREER COM		⁶ Well No. 1

⁷ Surface Location									
UL or lot no.	Section	Township	Range	Lot. Idn	Feet from the	North/South Line	Feet from the	East/West line	County
F	21	22S	36E		1650	NORTH	1980	WEST	LEA

⁸ Proposed Bottom Hole Location If Different From Surface									
UL or lot no.	Section	Township	Range	Lot. Idn	Feet from the	North/South Line	Feet from the	East/West line	County

⁹ Proposed Pool 1 LANGLEY STRAWN					¹⁰ Proposed Pool 2				
--	--	--	--	--	-------------------------------	--	--	--	--

¹¹ Work Type Code P	¹² Well Type Code 0	¹³ Cable/Rotary R	¹⁴ Lease Type Code FEE	¹⁵ Ground Level Elevation 3525.7
¹⁶ Multiple NO	¹⁷ Proposed Depth 16,302	¹⁸ Formation STRAWN	¹⁹ Contractor	²⁰ Spud Date 10/10/79

²¹ Proposed Casing and Cement Program

Hole Size	Casing Size	Casing weight/foot	Setting Depth	Sacks of Cement	Estimated TOC
17-1/2"	13-3/8"	54.5	1407'	1200	SURFACE
12-1/4"	9-5/8"	36	6230'	3600	SURFACE
8-3/4"	7"	29/26/23	16,300'	3225	ABOVE 9000'
<p>Permit Expires 1 Year From Approval Date Unless Drilling Underway Plugback</p>					

²² Describe the proposed program. If this application is to DEEPEN or PLUG BACK, give the data on the present productive zone and proposed new productive zone.
Describe the blowout prevention program, if any. Use additional sheets if necessary.

MIRUPU. NDWH. NU & TEST BOPE. PU 2-7/8" TBG. LOAD HOLE W/2X KCL. PRESS TST CSG TO 500 PSI & HOLD FOR 30 MINS. POOH W/KILL STRING. RUN GR/CLB/CCL 9400-8700' & CORRELATE. RIH W/7" SCRAPER & TBG TO 10,000'. SPOT 500 GALS 15% HCL W/ADD ACROSS STRAWN. POOH & LD SCRAPER. MIRU PERFORATORS. RIH W/4" CSG GUN W/2 SPF. PERF 8936-9334'. POOH W/GUNS. RD PERFORATORS. SET 7" TREATING PKR & SWAB TST STRAWN. MIRU ACIDIZERS. ACID FRAC STRAWN W/16,500 GALS. RDMO ACIDIZERS. FLOWBACK TO PIT UNTIL WELL DIES. REL PKR. POOH & LD. RUN 2-7/8" TBG. TAC. PMP W/GAS ANCHOR & RODS. SET PMP ABOVE PERFS @ +/- 8900'. ND BOPE. NUWH. RDMO.

²³ I hereby certify that the information given above is true and complete to the best of my knowledge and belief.

Signature: *Sabra Woody*

Printed name: SABRA WOODY

Title: ENGR TECH III

Date: 12/4/00

Phone: 915/683-0534

OIL CONSERVATION DIVISION

Approved by:

Title:

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐