

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2008

WELL API NO.

30-025-26075

5. Indicate Type of Lease

STATE ☐ FEDERAL ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Langley Greer Com

8. Well No.

1

9. Pool Name or Wildcat

Langley Devonian Gas

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

other

2. Name of Operator

ARCO OIL and GAS COMPANY

3. Address of Operator

P.O. Box 1610, Midland, Texas 79702

4. Well Location

Unit Letter F : 1650 Feet From The North Line and 1980 Feet from The West Line

Section 21

Township 22S

Range 36E

NMPM Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3525.7 GR

11.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

(Other) ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

(Other) ☐

12. Describe Proposed or completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-10-90. RUPU. POH w/tbg. Mill over model DB pkr at 12,310 & POH. Set CIBP at 12,525. Set pkr at 12,304. Swab test dev perfs 12,381-12,495. POH w/pkr. RIH w/CR & set at 12,111. Sqz dev perfs 12,381-12,495 w/200 sx H cmt. WOC. Tag TOC at 12,435. Re-sqz Dev perf 12,381-12,430 w/200 sx H cmt. WOC. Tag cmt at 12085. DO cmt to 12,525. Press test to 1000#. Ran CBL f/12,520-11520. Good cmt. Perf Dev. f/12,376-12466. A w/840 gals. Swab test. DO CIBP at 12,525. Swab test Dev perfs 12543-12606. Set CIBP at 12,520. Set CR at 12,400. EIR in Dev. Perfs 12415-12466. POH w/tbg. Leave CR at 12,400. RIH w/Otis Perma latch pkr on 2 7/8 tbg. Set pkr at 12,304. Swab Dev perf 12,376-12389. RDPU 7-3-90. Well shut in.

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE Ken W Gosnell TITLE Regulatory Coordinator DATE 2/11/91

TYPE OR PRINT NAME Ken W. Gosnell TELEPHONE (915) 688-5672

(This space for State Use)

Original
Paul E. ...
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS FOR APPROVAL, IF ANY: