Form 3 160-5 (June 1990)	UNITED DEPARTMENT O BUREAU OF LANI	F THE INTERIOR	N.M. Oil Cons. 1625 N. French Hobbs, NM 882	Dr. FORM Budget Burg 240 Expires: 1 5. Lease Designati		
Do not use th	SUNDRY NOTICES AND is form for proposals to drill or Use "APPLICATION FOR PE	o deepen or reent	ry to a different reservoir.	6. If Indian, Allon	0 61370B 03167CB ee or Tribe Name	
SUBMIT IN TRIPLICA TE				7. If Unit or CA, Agreement Designation		
Oil Sas Well Gas Well Other				8. Well Name and No. Bline by 1 SEMU # 101		
CONOCO INC. 3. Address and Telephone No.				9. APT Well No. 0 25		
10 DESTA DR. STE. 100W, MIDLAND, TX. 79705-4500 (915) 686-5424 4. Location of Well (Footage, Sec., T. R. M. or Survey Description)				30-045-26183 ¹⁰ Einthortt Vates & Rvis; Queen (76480)		
Section 29, T-20-S, R-38-E (5), 660 FNL & 330 FWL				11. County or Parish, State		
					Co., NM	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REFORT, OR OTHER DATA						
TYPE	TYPE OF SUBMISSION TYPE OF ACTION					
	stice of Intent	Abandonn	hent	Change of Pla	າກຮ	
ГТа				New Construc	tion	
L Su	bsequent Repon	Plugging I		Non-Routine	-	
Final Abandonment Notice		Casing Repair Altering Casing Other		Water Shut-Off Conversion to Injection		
				Dispose Water		
		ate ail pertinent details, and give pertinent dates, including estimated date of starting		INole: Reponresuitsof multiplecompitiononWal Completion or Recompletion Report and Log form.)		
 Conoco proposes MIRU pulling Pressure test of PU cement rei RU acid truck exceed 2000 p PU 7" packer Circulate inhii Remove the E Retest the cas Install tempor Pressure test t RU acidizing breakdown u Obtain ISIP, Unload the v Record rates 	to recomplete the Seven rivers in the vertical depther in the seven rivers in the seven and the seven rivers in the seven and the seven rivers in the seven rivers and the seven rivers at	his well using the fold d test per SOP. /8, 6.5#/ft, J-55 tbg. ration interval. Provid HCL with additives. ally pressure test tbg ackside. Set the pack the 2-7/8" x 5M ren manifold, 2-phase sep use injector head to lu various intervals fro l. Install treating line itives and ball sealers ent then go the test set D. Continue to test th	pertinent to this work.)* llowing procedure: ide adequate pressure relief so POOH. to 7,000 psig while TIH. to 7,000 psig while TIH. ter 60' above the top Seven R ted tree. parator and a flare stack. abricator. Test to 2,500 PSIG m 3000'-3300'. and N2 pop-off safety valve. as diverters. Tag w/Iridium. eparator. he well.	o as to not ivers perf. . TIH with		
A.	the foregoing is frue and correct	Kay Mad		- c.	ptember 20 ,2000	
Approved by / Conversion of appr Conversion of appr BLM(6), NMOCD(1	Ali or State office use i RIG, SGD.) ALEXIS C. SWOBO oval if any:), SHEAR, PONCA, COST ASST, FILE	DA Tide PET	ROLEUM ENGINEER	Date	DCT 1 2 2000	
or representations as to	1001, makes it a crime for any person knowing any matter within its junsdiction	iy and winituity to make to a	ary department or agency of the United S	states any false fictitio	us or fraudulent statements	

3

6

