Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill on the decrease and different different and decrease and different different and decrease an		Expires: March 31, 1993
		5. Lease Designation and Serial No.
		LC 031670B
		6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		
USE APPLICATION FO	H PEHMII—" for such proposals	
OHOMET IN TOIR IS A TO		7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE		
1. Type of Well		4
Well Well Other		8. Well Name and No.
2. Name of Operator		
Conoco, Inc.		Burger B-20 No. 1
3. Address and Telephone No.]
10 Desta Dr. Ste 100W, Midland, TX 79705		30-25-26393
		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Blinebry
1980' FNL & 1980' FWL		11. County or Parish, State
Sec. 20, T-20S, R-38E		1
·		Lea, NM
12. CHECK APPROPRIATE BOY	s) TO INDICATE NATURE OF NOTICE, REPOF	T OP OTHER DATA
	s) TO INDICATE NATURE OF NOTICE, REPOR	II, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent		
Notice of Intent	Abandonment	Change of Plans
\Box	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other Renew Temporary	Dispose Water
	Abandonment	(Note: Report results of multiple completion on Well
13. Describe Proposed or Completed Operations (Clearly state a	I pertinent details, and give pertinent dates, including estimated date of starting	Completion or Recompletion Report and Log form.)
2	porary abandonment of this well for any test of 12/20/91. d on offset wells evaluating the resulound to be cost effective, well No. 70 JAN 0 8 13	ts of re-fracing will be re-fraced
4. I hereby conflict that the forestoute is used and correct Signed	Title Sr. Conservation Coordinator	r Date 12/15/95
This speed for CONIG SECO. SOF G. LA	Title	Date 2/5/96
Conditions of approval, if any: See atta	ched.	-

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Rev: 1/12/95)

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

Temporary Abandonment (TA) status approval requires: A) Successful Casing Integrity Test and, B) Successful Bradenhead Test.

Any temporary abandonment request must be submitted on a Sundry Notice (Form 3160-5), one (1) original signature and five (5) copies, and include the following:

- 1. Justification why the well should be temporarily abandoned rather than permanently plugged and abandoned.
- 2. Description of the temporary abandonment procedure.
- 3. A complete wellbore diagram shown as temporarily abandoned.
 4. The anticipated date the operations will occur.

Contact the appropriate BLM office at least 48 hours prior to the scheduled Casing Integrity and the Bradenhead Tests. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.

A) Casing Integrity Test for TA:

- 1. Install an isolation device (such as a retainer or bridge plug) within 50' to 100' of the top perforation or cement plug that extends at least 50' above each set of open perforations. Unless prior approval is granted by the Authorized Officer, fill the well bore with conditioned, noncorrosive fluid and shut-in at the surface. If a cement plug is used, the top of the cement must be verified by tagging. If the wellbore had more than one producing horizon, the lower set(s) of perforations or open hole must meet the requirements for permanent plug to abandonment, unless justification is provided by the operator not to do so.
- 2. A test demonstrating casing mechanical integrity is required. An approved method is a pressure test of the casing and uppermost plug. The pressure test conducted shall be a minimum of 500 psi surface pressure with less than 10 percent pressure drop within thirty (30) minutes. In no event shall the pressure test required exceed seventy (70) percent of the internal yield of the casing. In the case of an unsuccessful test, the operator shall either correct the problem or plan to plug and abandon the well. Alternative methods demonstrating casing mechanical integrity may be approved by the Authorized Officer on a case-by-case basis.

B) Bradenhead Test for TA:

- 1. Record the pressure measured on each casing string, including intermediate casing, using deadweight or calibrated pressure gauge.
- 2. Open the bradenhead valve to the atmosphere. If gas or water flow is observed or indicated, flow the bradenhead for a minimum of fifteen (15) minutes and record pressures at five (5) minute intervals on the production, intermediate and surface casing. Describe in detail any fluids flowing from the bradenhead including measured or estimated rates of flow. A water and/or gas analysis may be required.

Wells that successfully pass the casing integrity test and the bradenhead test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits within thirty (30) days a subsequent Sundry Notice (one (1) original signature and five (5) copies) requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test charts,
- If the well does not pass the casing integrity test and/or the bradenhead test, then the operator shall within 90 days submit to BLM for approval one of the following:
- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.