

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.		30-025-26628	
5. Indicate Type of Lease		STATE <input checked="" type="checkbox"/>	FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.		157	
7. Lease Name or Unit Agreement Name			
State 157 D			
8. Well No.		15	
9. Pool name or Wildcat			
Drinkard			
0		Feet From The	West
			Line
MPM		Lea	County

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		State 157 D
2. Name of Operator ARCO Oil and Gas Company		8. Well No. 15
3. Address of Operator P.O. Box 1710 - Hobbs, New Mexico 88241-1710		9. Pool name or Wildcat Drinkard
4. Well Location Unit Letter <u>M</u> : <u>660</u> Feet From The <u>South</u> Line and <u>940</u> Feet From The <u>West</u> Line Section <u>12</u> Township <u>22S</u> Range <u>36E</u> NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3497.1 GR</u>		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER:			<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Abandon Drinkard ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 6800', PBD 6742', Perfs 6619-6188'

Set CIBP @ 6600'. Load well w/2% KCL and test to 500# for 30 minutes.

Witnessed by Charlie Parren - NMOCD

Chart Attached

Zone Abandoned 12/29/92. 12/31/92 - Dump 35' cement on CIBP @ 6600'. Set CIBP @ 3950' with 35' cement on top.

- Shut In. Evaluate recompletion in Eumont.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Operations Coordinator DATE 01/11/93
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. (505) 391-1600

(This space for State Use)

ORIGINAL SONGS BY JERRY SEALED
DISTRICT OF COLUMBIA

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 12 1993

OCD HOBBS OFFICE