

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator ARCO OIL & Gas Company Division of Atlantic Richfield Company	8. Farm or Lease Name W.C. Roach
3. Address of Operator P.O. Box 1710 Hobbs, New Mexico 88240	9. Well No.
4. Location of Well UNIT LETTER <u>K</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>West</u> LINE, SECTION <u>21</u> TOWNSHIP <u>20S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Eumont Yt 7R Qn Gas/ Eunice Monument Grbg SA
15. Elevation (Show whether DF, RT, GR, etc.) 3508.7 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <u>TA GRBG SA</u>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Eumont perfs 3476--3620 & Eunice Monument GB/SA perfs 3758--3930'

1. POH w/rds & pmp
2. Install BOP & POH w/tbg and pkr
3. RIH w/bit & scraper
4. RIH w/CIBP & pkr
5. Set CIBP + or - 3710'
6. Test CIBP w/1000 PSIG
7. Pull pkr up hole & set + or - 3450'

Work to begin on approval

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Paul Kautz</u>	TITLE <u>Services Supv.</u>	DATE <u>4-19-88</u>
APPROVED BY <u>Paul Kautz</u> Geologist	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

APR 19 1988
OCD
HOBBS OFFICE