

SKIPPED PRESSURES ($P_i^2 - P_w^2$)
(1000 psia)


1000

100

10

$$\begin{aligned} \log 4900 (q_1) &= 3.6902 \\ \log 490 (q_2) &= 2.6902 \\ n &= 1.0000 \end{aligned}$$

$$P_{0.1} = 55.32$$



FLOW RATE (MCF/d)

$P_{1000} = 508.7 = P_{0.001}$