

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. <b>30-025-26959</b>	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name: <b>McDonald State A/C 2</b>	
8. Well No. <b>#34</b>	
9. Pool name or Wildcat <b>South Eunice (7 Rivers/Queen) Unit</b>	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator **Marathon Oil Company**

3. Address of Operator  
**P.O. Box 2490, Hobbs, NM 88240**

4. Well Location  
Unit Letter **C** : **660** feet from the **North** line and **2,310** feet from the **West** line  
Section **13** Township **22** ~~13-S~~ Range **36-E** NMPM County **Lea**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**3,483' GL; 3,495' KB**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See attached wellbore diagram.

1. Dig & line earthen work pit, flow well down as needed. MIRU. NU BOP, release packer and POOH standing back production tbg.
2. RIH w/ production tubing and workstring to 6,500'. Load hole w/ plugging mud.
3. POOH w/ tbg to 5,500', pump 25 sx C cmt @ 5,500'. **Blinebry plug**
4. POOH w/ tbg to 3,500'. Load hole w/ mud and pump 25 sx C cmt w/ 2% CaCl<sub>2</sub> @ 3,500'. WOC & tag no deeper than 3,400'.
5. POOH w/ tbg to 2,666' and pump 25 sx C cmt @ 2,666'. **Yates (2,616') plug**
6. POOH w/ tbg to 1,370'. Pump 25 sx C cmt @ 1,370'. **csg shoe plug**
7. Pump 10 sx C cmt 50' to surface. **surface plug**
8. Cut off wellhead and install dryhole marker. Cut off anchors and level location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE **Engineer** DATE **06/21/02**

Type or print name **James F. Newman, P.E.** Triple N Services, Inc. Telephone No. **915-687-1994**  
(This space for State use)

APPROVED BY \_\_\_\_\_  
Conditions of approval, if any: \_\_\_\_\_

TITLE \_\_\_\_\_  
ORIGINAL SIGNED BY **GARY W. WINK**  
O.C. FIELD REPRESENTATIVE II/STAFF MANAGER  
DATE **JUN 27 2002**