

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-26976

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

L-4780

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

POGO PRODUCING COMPANY

3. Address of Operator

P. O. BOX 10340, MIDLAND, TEXAS 79702

4. Well Location

Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line

Section 18 Township 22-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☒

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Division Operations Manager DATE 12/30/96

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY
JUDY WINK
FIELD REP. II

APPROVED BY

TITLE

DATE

JAN 08 1997

mp

POGO NBR STATE WELL NO. 1
1980' FSL and 1980' FEL
Section 18, T-22-S, R-33-E
Lea County, New Mexico

Page 1

P: AtkBk 13756-765'
P: Atk 13865-895'
P: Mrw 14739-763'

Re-establish Atoka Bank Production

TD 15120' CIBP 13910' CIBP 13845'

11/25/96 MIRU WSU, prep to release packer.
11/26/96 Rls pressure, POOH, found 2 jt w/ hole; XO BOP gasket.
TIH w/ pkr, drop SV, tbg failed to test, POOH. SDFN.
11/27/96 Test tbg to 8500 PSI, set pkr @ 13445'.
11/28-29/96 SD for Thanksgiving.
11/30/96 Move pkr to 13069'. Cmt sqz Atoka perfs.
12/01/96 POOH pkr, tag cmt @ 13068', drl to 13130'.
12/02/96 Drl cmt.
12/03/96 Drl cmt & junk 13849-13860'
12/04/96 Trip for new bit, make up shoe & TIH.
12/05/96 Mill on CIBP @ 13860', stuck @ 13888', worked free,
continue to work BP dn hole but shoe was dragging in csg,
POOH.
12/06/96 Bleed csg & tbg & finish POOH. SI well for day to build
fishing tool.
12/07/96 TIH to 13888', mill on BP & push dn hole (short 13').
12/08/96 Push BP to 13911', ran GR 13915-13370'.
12/09/96 Drl junk @ 13890-13891.
12/10/96 Mill 13891-13899', circ hole clean, TOOH tbg & mill.
12/11/96 Test tbg.
12/12/96 Set pkr @ 13791', disp hole w/ brine. Swab.
12/13/96 Swab.
12/14-15/96 SDFWE, prep to swab.
12/16/96 Swab.
12/17/96 POOH tbg.
12/18/96 TP Ø. POOH pkr & sent for repair (?nothing wrong).
12/19/96 Test tbg to 10000 PSI, hold 1 min.
12/20/96 Test tbg to 10000 PSI, hold 1 min. Set pkr @ 13788'.
12/21/96 Circ pkr fluid, test pkr to 500 PSI 30 min (OK). Swab.
12/22/96 Swab, possible paraffin plug @ 10500'.
12/23/96 Swb to obstruction @ 10000', pmp condensate dn tbg,
communication established w/ annls when pressure reached
4300 PSI, apparent tbg leaking @ 13744-13765'. Made 1
more swb run, plg still in tbg @ 10000'.
12/24/96 SD, WOO.
12/25/96 SD for Christmas, WOO.
12/26/96 RDMO service unit, WOO.

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-26976
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	L-4780

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

NBR State

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

POGO PRODUCING COMPANY

8. Well No.

1

3. Address of Operator

P. O. BOX 10340, MIDLAND, TEXAS 79702

9. Pool name or Wildcat

Bootleg Ridge *Atoka*

4. Well Location

Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line
Section 18 Township 22-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Edward L. Smith

TITLE

Division Operations Manager

DATE

12/03/96

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL FILED IN 100-100000-100000

DEC 09 1996

APPROVED BY

TITLE

DATE

POGO NBR STATE WELL NO. 1
1980' FSL and 1980' FEL
Section 18, T-22-S, R-33-E
Lea County, New Mexico

Page 1

P: AtkBk 13756-765'
P: Atk 13865-895'
P: Mrw 14739-763'

Re-establish Atoka Bank Production

TD 15120' CIBP 13910' CIBP 13845'

11/25/96 MIRU WSU, prep to release packer.
11/26/96 Rls pressure, POOH, found 2 jt w/ hole; XO BOP gasket.
TIH w/ pkr, drop SV, tbg failed to test, POOH. SDFN.
11/27/96 Test tbg to 8500 PSI, set pkr @ 13445'.
11/28-29/96 SD for Thanksgiving.
11/30/96 Move pkr to 13069'. Cmt sqz Atoka perfs.
12/01/96 POOH pkr, tag cmt @ 13068', drl to 13130'.
12/02/96 Drl cmt.