

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Budget Bureau No. 44-01  
Expires August 31, 1985  
5. LEASE DESIGNATION AND SERIAL NO.

0290025110

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
Conoco Inc.

3. ADDRESS OF OPERATOR  
P.O. Box 460 - Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1750' FNL & 710' FEL

14. PERMIT NO.  
30-025-2698300

15. ELEVATIONS (Show whether DF, RT, CR, etc.)  
3508' DF

7. UNIT AGREEMENT NAME  
SEMU Eumont

8. FARM OR LEASE NAME  
SEMU Eumont

9. WELL NO.  
No. 118Y

10. FIELD AND POOL, OR WILDCAT  
Eumont Queen Gas

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 27 T20S R37E

12. COUNTY OR PARISH  
Lea

13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) \_\_\_\_\_

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATION. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. MIRU. ND wellhead and NU BOP.
2. Set CIBP @ 3400'. Load and Circ. hole w/85 bbls mud. Spot 25 sx cement on CIBP.
3. Spot cement plug from 1240' to 1340'. WOC.
4. ND BOP and cut off all casing strings at the base of the cellar. Erect an abandonment marker.

For further technical information contact Neal Hoover at 397-5858.

18. I hereby certify that the foregoing is true and correct

SIGNED W.W. Baker TITLE Administrative Supervisor DATE July 22, 1989

(This space for Federal or State office use)

APPROVED BY James J. Shaw FOR: James J. Shaw DATE 8-15-89  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side