ubmit 3 Copies > Appropriate Pistrict Office		New Mexico atural Resources Department	Form C-103 Revised 1-1-89
USTRICT I .O. Box 1980, Hobbs, NM 88240	OIL CONSERV	ATION DIVISION Box 2088	WELL API NO.
ISTRICT II O. Drawer DD, Artosia, NM \$8210	Santa Fe, New M	Mexico 87504-2088	5. Indicate Type of Lease STATE FEE X
DISTRICT III 000 Rio Brazos Rd., Aztec, NM 8741	10		6. State Oil & Gas Lease No.
DO NOT USE THIS FORM FOR I DIFFERENT RE	OTICES AND REPORTS ( PROPOSALS TO DRILL OR TO SERVOIR. USE "APPLICATION M C-101) FOR SUCH PROPOSA	DEEPEN OR PLUG BACK TO A FOR PERMIT"	7. Lease Name or Unit Agreement Name
Type of Well: OIL CAS WELL X WELL			Speight
Name of Operator			8. Well No.
Tamarack Petroleum	i Company, Inc.		9. Pool name or Wildcat
Address of Operator 500 W. Texas, Suit	e 1485, Midland, TX	79701	W. Nadine Blinebry
. Well Location			60 Feet From The West L
		,	Tee
Section 9	Township 20S	Range 38E	NMPM Lea County
	10. Elevation (Sho 3588' F	w whether DF, RKB, RT, GR, etc.) KB	
· · · · · · · · · · · · · · · · · · ·	ck Appropriate Box to In		Report, or Other Data
	INTENTION TO:	SI	IBSEQUENT REPORT OF:
	-		_
ERFORM REMEDIAL WORK	PLUG AND ABANDO		
	CHANGE PLANS		
EMPORARILY ABANDON			
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:Open	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Additional Blinebry pay
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:Open	
EMPORARILY ABANDON	CHANGE PLANS Derations (Clearly state all pertinent aper to 6609', circ ditional Blinebry pa 07'-6137' (9 holes) holes). x old perfs with 10 packer. load, pulled RBP and	COMMENCE DRILLI CASING TEST AND OTHER: Open details, and give pertinent dates, in frac sand out of he ay as follows: 5879 ,6194'-6263' (13 hol ,550 gals 15% NEFE a d packer.	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB additional Blinebry pay cluding estimated date of starting any proposed
EMPORARILY ABANDON	CHANGE PLANS CHANGE PLANS Derations (Clearly state all pertinent aper to 6609', circ ditional Blinebry pa 07'-6137' (9 holes) holes). x old perfs with 10, packer. load, pulled RBP and imp & rods - returned	COMMENCE DRILLI CASING TEST AND OTHER: Open details, and give pertinent dates, in frac sand out of ho ay as follows: 5879 ,6194'-6263' (13 hol ,550 gals 15% NEFE a d packer. ed well to prod.	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB additional Blinebry pay duting estimated date of starting any proposed ole. 0'-5932' (10 holes), 5942'-5943 Les), 6308'-6332' (6 holes), acid, isolating selected zones
EMPORARILY ABANDON JIL OR ALTER CASING THER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 1. Ran bit & scra 2. Perforated add (6 holes), 610 6383-6413' (8 3. Acidized new & with RBP plus 4. Swabbed back 1 5. Ran tubing, pu Note: Work wa	CHANGE PLANS CHANGE PLANS Derations (Clearly state all pertinent aper to 6609', circ ditional Blinebry pa 07'-6137' (9 holes) holes). x old perfs with 10, packer. load, pulled RBP and imp & rods - returned	COMMENCE DRILLI CASING TEST AND OTHER: Open details, and give pertinent dates, in frac sand out of ho ay as follows: 5879 ,6194'-6263' (13 hol ,550 gals 15% NEFE a d packer. ed well to prod.	PLUG AND ABANDONMENT CEMENT JOB additional Blinebry pay cluding estimated date of starting any proposed ple. p'-5932' (10 holes), 5942'-5943 Les), 6308'-6332' (6 holes),
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Open details, and give pertinent dates, in frac sand out of he ay as follows: 5879 ,6194'-6263' (13 hol ,550 gals 15% NEFE a d packer. ed well to prod.	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB additional Blinebry pay duting estimated date of starting any proposed ole. 0'-5932' (10 holes), 5942'-5943 Les), 6308'-6332' (6 holes), acid, isolating selected zones
EMPORARILY ABANDON JIL OR ALTER CASING THER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 1. Ran bit & scra 2. Perforated add (6 holes), 610 6383-6413' (8 3. Acidized new & with RBP plus 4. Swabbed back 1 5. Ran tubing, pu Note: Work wa	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Open other: Open other: Open other: Open other: Open other: Open other: Open other: Open of details, and give periment dates, in frac sand out of he ay as follows: 5879 ,6194'-6263' (13 hol ,550 gals 15% NEFE a d packer. ed well to prod. 05. Notice of inter	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB additional Blinebry pay cluding estimated date of starting any proposed ole. 0'-5932' (10 holes), 5942'-5943 les), 6308'-6332' (6 holes), acid, isolating selected zones htion was not given.
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Open details, and give pertinent dates, in frac sand out of he ay as follows: 5879 ,6194'-6263' (13 hol ,550 gals 15% NEFE a d packer. ed well to prod.	NG OPNS.  PLUG AND ABANDONMENT    CEMENT JOB
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Open other: Ope	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB additional Blinebry pay cluding estimated date of starting any proposed ole. 0'-5932' (10 holes), 5942'-5943 les), 6308'-6332' (6 holes), acid, isolating selected zones htion was not given.