

WELL INCLINATION SURVEY

I, Randy A. McClay, certify the following is the correct hole inclination survey for the well as described below:

Tamarack Petroleum Company, Inc., _____
(Company or Operator) (Lease)

Speight Well No. 1

in NW 1/4 of NW/4, of Sec 9, T 20-S,

R 38-E, NMPM. _____ Pool, _____

Lea County. Well is 660 feet from the _____

North line and 660 feet from the West line of

Section 9.

Depth(Feet)	Inclination(Degree)	Depth(Feet)	Inclination(Degree)
159	1/4	4055	1 3/4
313	1	4241	1 1/2
497	1/2	4425	1 1/2
650	1/4	4508	2
803	1/2	4672	1 3/4
1015	1	4858	3 1/4
1284	1 3/4	4950	3 1/2
1438	3/4	5041	4
1600	1/4	5132	4 1/4
1843	1/2	5224	4 3/4
2118	3/4	5346	4 3/4
2365	1	5401	4 3/4
2609	2	5455	4 3/4
2794	3	5518	4 3/4
2855	2 3/4	5579	4 3/4
2917	2 3/4	5693	4 3/4
2979	2 3/4	5704	4 3/4
3041	3	5765	4 1/2
3120	2	5825	4 1/2
3220	3	5886	4
3406	2 3/4	5946	4 3/4
3497	2 3/4	5979	4 3/4
3591	2		
3714	2		
3920	2 1/2		

continued on next page

Tamarack Petroleum Company, Inc.
(Company or Operator)

By Randy A. McClay

Title District Engineer

Subscribed and sworn to before me
this 3rd day of November,
19 80.

Judy Robbins
Notary public in and for Midland
County, Texas.

