

UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW MEXICO

CATE
on re-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <i>Conoco Inc</i>	8. FARM OR LEASE NAME <i>Warren McKee</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, NM</i>	9. WELL NO. <i>88</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>660' FS & 660' FWL - Unit Letter M</i>	10. FIELD AND POOL, OR WILDCAT <i>Warren McKee</i>
14. PERMIT NO. <i>30-025-27246</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>29-20S-38E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <i>3511.2' GR</i>	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) *Open Add'l Pay & Acidize*

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started 3/23/87. MIRR. Tag top of fill at 9140'. Clean out to 9195' (PBTD). P.O. H. w/ Hg & scraper. Set RBP at 9055'. Pull Hg up hole to 9030'. Load hole w/ 160 BTFW. Pump 20 bbl 15% HCL-NE-FE acid down Hg to clean Hg. Flush w/ 52 BTFW. Reverse acid out Hg. Release RBP & reset at 9188'. Spot 4 bbls 15% HCL-NE-FE from 9188'-9050'. Load csq w/ 105 BTFW & pressure up to 500 psi. Acidize McKee perf w/ 50 bbls 15% HCL-NE-FE acid in 2 equal stages. Divert between stages w/ 100# salt mixed in 2 bbl 10 ppq brine w/ 3 lbs Guar gum. Flush to btm perf w/ 57 BTFW. Swab well. Work Completed 5/2/87.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(For use by Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

AUG 7 1987

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO

Title 31, U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

B.L.M. (Carlsbad) 6-ARCO (2) Amoco (2) Chevron (1) File

RECEIVED

AUG 10 1987

**OCD
HOBBS OFFICE**