		Form C-103
NO. OF COPIES RECEIVED		Supersedes Old C-102 and C-103
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	
FILE		5a. Indicate Type of Lease
U.S.G.S.		State Fee X
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		
SUND	RY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR THE USE "APPLICAT	(T INU LICES AND ALL AND ALL AND ALL BACK TO A DIFFERENT RESERVOIR. OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. FION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
	OTHER.	8. Farm or Lease Name
2. Name of Operator		Harkins
Tamarack Petroleum Co., Inc.		9. Well No.
3. Address of Operator	J TV 70702	1
P. O. BOX 2046, Midland, TX 79702		10. Field and Pool, or Wildcat
4. Location of Well		W. Nadine Blinebry
A A	660 FEET FROM THE NORTH LINE AND 660 FEET FRO	
UNIT LETTER	00 C 20 E	
east une sect	10N 8 20-S RANGE 38-E NMP	w.XIIIIIIIIIIIIIIIIIIIII
THE LINE, SECT		12. County
	15. Elevation (Show whether DF, RT, GR, etc.)	Lea
X/////////////////////////////////////	3579.2 GR	
16. Check	Appropriate Box To Indicate Nature of Notice, Report or C	Other Data
CIECK	INTENTION TO:	NT REPORT OF:
NOTICE OF	IN LENTION TO:	F
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON		
PULL OR ALTER CASING	CHANGE PLANS	Recompletion
OTHER		
	Operations (Clearly state all pertinent details, and give pertinent dates, includ	ing estimated date of starting any propose

- work) SEE RULE 1103.
 - 10-14-81 Nipple up BOPE. Pull out of hole with rods, pump and tubing. Set CIBP at 6850. Put 35' cement on plug.
 - 10-16-81 Perforate casing with one casing jet per foot @ 5999, 6001 (2 holes), 6007, 6009, 6014, 6016, 6018, 6020, 6022, 6024, & 6026 (12 holes). Run in hole with Model R Packer on 2 3/8" tubing.
 - 10-17-81 Nipple down BOPE and nipple up wellhead. Set packer at 5897. Acidize with 3000 gallons DS-30 acid and 24 ball sealers. Treated 4 BPM with 4000 PSI. Ball out to 5100 PSI. ISIP 2700 PSI flow well back to clean up.
 - 10-20-81 Frac with 40,000 gal gelled 27₀ KCL water and 24,000# 20/40 sand. Treated 10 BPM with 5400 PSI. ISIP 3100 PSI 15" SIP 2400 PSI.

10-22-81 Put on pump.

18. I hereby certify that the information above is true and complet	te to the best of my knowledge and belief.	
SIGNED Randy J. Millay	District Engineer	DATE October 27, 1981
Orig Signed by Les Clinents APPROVED BY OIL & Gas Instr CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE M