WELL INCLINATION SURVEY

I, <u>Randy A. McClay</u>, certify the following is the correct hole inclination survey for the well as described below:

	Petroleum	<u>Company</u>	Inc.		,	Harkins(Lease)	
				No1			
in NE	1/4 of	NE/4	_, of Se	c8	_,T _	-20 - S	,
R38-E	, NMPM		Skaggs Drinkard		Pool,		
	Lea	_County.	Well is	660	feet	from the_	
North	_line and	660	fee	et from the _	East	line	e of
Section	8	-					
Depth(Feet)	Incl	ination (De	egree)	Depth(F	'eet)	Inclinati	ion(Degree)
$ \begin{array}{c} 0 \\ 263 \\ 585 \\ 1028 \\ 1330 \\ 1600 \\ 1842 \\ 2100 \\ 2357 \\ 2600 \\ 2731 \\ 2823 \\ 3070 \\ 3349 \\ 3629 \\ 3840 \\ 4158 \\ 4406 \\ 4684 \\ 4962 \\ 5272 \\ 5470 \\ 5732 \\ 5981 \\ 6507 \\ 6818 \\ 7100 \\ \end{array} $		1/2 3/4 1/2 1/2 1/4 1/4 1/4 2 2 1/4 2 1 1/4 1 1 1/4 1 1 1/4 1 1/4		(Co By Ra m	Petrole mpany trict E	eum Compan or Operation A. Ma ngineer	y, Inc. or).
Subscribed this <u>20</u> 19 <u>81</u> .				, ,			
Diane Hell	man Du	internationalist	Hellin	nan			

Notary public in and for Midla County, Texas.

.