

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Tamarack Petroleum Co., Inc.		8. Farm or Lease Name Holway
3. Address of Operator P. O. Box 2046, Midland, TX 79702		9. Well No. 1
4. Location of Well UNIT LETTER 0 660 FEET FROM THE south LINE AND 1980 FEET FROM THE east LINE, SECTION 5 TOWNSHIP 20-S RANGE 38-E NMPM.		10. Field and Pool, or Wildcat W. Nadine Blinebry
15. Elevation (Show whether DF, RT, GR, etc.) 3582.4 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in rig up pulling unit on or about May 1, 1985
2. Pull out of hole with rods pump and tubing
3. Set retrievable bridge plug at 5960+
4. Perforate Upper Blinebry Pay from 5922 to 5936 with 10 casing jet shots
5. Set Baker Model R Packer at 5900+ and acidize w/2500 gallons 15% HCL
6. Swab flow or pump test
7. Pull out of hole with retrievable bridge plug and put on pump

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Randy A. McClary TITLE Engineering Manager DATE 4/23/85

APPROVED BY DAVID L. HARRIS TITLE Commissioner DATE

CONDITIONS OF APPROVAL, IF ANY: