WELL INCLINATION SURVEY

I, <u>Randy A. McClay</u>, certify the following is the correct hole inclination survey for the well as described below:

Tamarack Petroleum Co., Inc. (Company or Operator)				_,Pewitt (Lease)	
		Well No.			
in <u>NE</u>	1/4 ofSE/4	_, of Sec	<u>8</u> ,T	20-S ,	
R <u>38-E</u>	, NMPM. <u>sk</u>	aggs-Drinkard	Poo	ol,	
Lea	County.	Well is	<u>980</u> feet	from the	
south	line and 660	feet from	n theeast	tline of	
Section	8•				
Depth(Feet)	Inclination(De	gree) D	epth(Feet)	Inclination(Degree	
421 1150 1537 1568 2103 2481 2868 3363 3856 4350 4543 5188 6130 6830 7080	3/4 1/2 1/2 3/4 3/4 1/4 3/4 1/2 1/2 3/4 1 3/4 1 3/4 1 3/4 1 3/4 1 3/4				
		By Title	(Company	C PEtroleum Co., Inc. or Operator) 7. M. Clay t Engineer	
Subscribed this <u>22nd</u> 19 <u>81</u> .	and sworn to befor day of <u>Septembe</u>		۲		
Notary publ County, Te	Long Judy Rob lic in and for Midla xas.	<u>bins_</u> nd			

Commission expires 8/17/85.

