

OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2080
SANTA FE, NEW MEXICO 87501

5
Form C-101
Revised 10-1-73

API 30-025-27466

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A WELL TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☐

CAS WELL ☒

OTHER ☐

Name of Operator

Penroc Oil Corporation

Address of Operator

P. O. Box 5970, Hobbs, NM 88241

Location of Well

UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 22S RANGE 33E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

GR 3591.3

30. Indicate Type of Lease	
State ☒	For ☐
3. State Oil & Gas Lease No.	
NM 1249	
7. Unit Agreement Name	
State 7 SST	
8. Firm or Lease Name	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Bootleg Ridge Morrow	
12. County	
Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

50 sx at 14,000 on top of CIBP 5"
50 sx at 11,810 TOC 11630
25 sx at 8740
60 sx at 6034 TOC 5933 tagged
120 sx at 4900 WOC no tag
60 sx at 4800 WOC Tag at 4699
60 sx at 1100
10 sx at surf

PLUGGING WAS WITNESSED BY NMOCB - MR. SADLER

I, hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed James Williams James Williams

TITLE Manager

DATE 10-30-89

APPROVED BY R. A. Sadler

TITLE OIL & GAS INSPECTOR

DATE 10-30-89

CONDITIONS OF APPROVAL, IF ANY:

1
R

5

RECEIVED

NOV 15 1991

000

NOBBS OFFICE

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27466

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
NM 1249

7. Lease Name or Unit Agreement Name

STATE 7 SST

8. Well No.

1

9. Pool name or Wildcat

Bootleg Ridge Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
PENROC OIL CORPORATION

3. Address of Operator
P.O. Box 5970, Hobbs, NM 88241

4. Well Location
Unit Letter J : 1980 Feet From The SOUTH Line and 1980 Feet From The EAST Line
Section 7 Township 22S Range 33E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GR. 3591.3

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug & abandon as follows by Sept. 30, 1989
Rig up plugging rig. Set plug in Baker Model DB or a CIBP. @
14000'. 50 sxs. cement plug on top. Load hole w/ 10[#] gelled brine.
Spot 50 sxs. Cement plug across 5" Liner top @ 11,776'. Tag plug.
Pull approximately 9000' of 7^{5/8"}, 33.7[#] N-80 csg. Spot 100'
cement plug across stub (50[#]-50[#]). Spot 50 sxs. plug across
Bonespring (50'-50'). Spot 50' cement plug across Delaware (4900').
Spot 50 sxs. plug across salt top (1050'). Set 10 sxs. surface plug.
Install marker. Cut deadman. Clean up location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE August 7, 1989

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 8 1989

CONDITIONS OF APPROVAL, IF ANY: