WELL INCLINATION SURVEY

I, <u>Randy A. McClay</u>, certify the following is the correct hole inclination survey for the well as described below:

Tamarack ((Petroleum (Company,] r Operato		,(Lease)			
				o1			
inSW	_1/4 of	SE/4	_, of Sec	8	_,T	20-S	>
R <u>38-E</u>	, NN	мрм	W. Nadin	e (Blinebry	/)Pool,		
Lea		County.	Well is	660	feet fi	com the	
south	_line and _	_2310	feet	from the _	east	line	of
Section	8	-		•			
Depth(Feet)	Incli	nation (De	egree)	Depth(F	eet)	Inclinatio	on(Degree)
350 881 1350 1575 2028 2525 2850 3022 3330 3610 4074 4540 5200 5715 6332 7107		1/2 3/4 1/2 1/4 1/4 1 1/2 2 1 3/4 1 1/2 3/4 1/4 3/4 1 2 1/4 2 1 3/4	·		•		
				(Con		troleum Co Operato I. M ineer	
Subscribed this <u>12</u> 19 <u>81</u> . Vanessa K	<u>eth</u> day of	to befor October	e me , K M	ilie			•
Notary pub County, Te	lic in and :	for Midla	nd				