

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27564
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. LG-4136
7. Lease Name or Unit Agreement Name San Simon "5" State
8. Well No. 1
9. Pool name or Wildcat San Simon (Wolfcamp)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Mitchell Energy Corporation	
3. Address of Operator Box 4000, The Woodlands, TX 77387	
4. Well Location Unit Letter <u>E</u> : <u>660</u> Feet From The <u>West</u> Line and <u>1980</u> Feet From The <u>North</u> Line Section <u>5</u> Township <u>22S</u> Range <u>35E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3641' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to POOH w/2 1/2 tbg. RU WL. RIH w/dump bailer & dump 35' cmt on DB pkr w/plug @ 11,528'. RIH w/CIBP & set @ 10,650'. RIH w/tbg to 10,650'. Spot 100' of cmt across liner top. Tag plug. Displace hole w/9.5# mud. POOH w/tbg. Cut csg @ ±5600'. POOH w/7" csg. RIH w/tbg to 8000'. Spot 100' cmt plug. Tag plug. PU to 5675'. Spot 100' plug across 9 5/8" shoe & csg cut. Tag plug. POOH w/tbg. Spot 10 sx plug @ surface. Cut off csg head & weld on P&A marker. Clean location.

100' plug at ~~top~~ base of salt
100' plug @ Top of salt

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James Blount TITLE Engineer DATE 7/20/94
TYPE OR PRINT NAME James Blount TELEPHONE NO. (915) 682-5396

(This space for State Use)

ORIGINAL SIGNED BY ERRY DEXTON
DISTRICT I SUPERVISOR

JUL 28 1994

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: