

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN T
(Other Instruc
Reverse Side)

RECEIVED
LC-031695 (B)
4MS

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

MAR 5 8 03 AM '90

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CARL
AREA

7. UNIT AGREEMENT NAME

Warren Unit BL. Bty 1

8. FARM OR LEASE NAME

3. ADDRESS OF OPERATOR

P.O. Box 460 - Hobbs, NM 88240

9. WELL NO.

#91

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

Unit F

1650' FNL & 2310' FWL

10. FIELD AND POOL, OR WILDCAT

Blinberry Oil & Gas

11. SEC., T., R., or BLK. AND
SURVEY OR AREA

Sec. 33, T20S, R38E

14. PERMIT NO.

30-025-27566

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3513'

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

Open add'l pay

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Install BOP. Perforate Blinberry zones 4 & 5 as follows:

Zone 4: 6152', 56', 62', 66', 71', 76', 6188', 90', 92', 94', 96', 6200',
03', 07', 10', + 13' (16 holes)

Zone 5: 6261', 65', 73', 75', 79', 81', 83', + 89' (8 holes) w/1 JSPF

Set pki. @ 6075'. Pump 30 bbls HCl-NE-FE w/45 balls/valves.

Fracture w/45,000 gals 16-30 Ottawa, a total sand wt.

of 91,500 lbs.

Swab. Return to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

HA Ingram

TITLE

Conservation Coordinator

DATE

2/28/90

(This space for Federal or State office use)

APPROVED BY

Orig. Signed by

CONDITIONS OF APPROVAL, IF ANY:

TITLE

PETROLEUM ENGINEER

DATE

3-9-90

*See Instructions on Reverse Side