## WELL INCLINATION SURVEY

I, <u>Randy A. McClay</u>, certify the following is the correct hole inclination survey for the well as described below:

	Tamarack Petroleum Company, Inc. (Company or Operator)				, (Lease)			
	Raley "A"							
in	_SE1/4 of	SE/4	_, of Sec	88	_,T	20-S	_?	
R	<u>38-E</u> , 1	NMP <b>M.</b>	W. Nadir	1e	Pool,_			
	Lea	County.	Well is	990	feet fro	om the		
	south line and	d <u>990</u>	feet	from the $\_$	east	line of		
Section	n 8	<b>.</b>						
Depth(	Feet) Inc	lination <b>(</b> De	gree)	Depth(F	eet) I	nclination(E	)egre <b>e)</b>	
200 500 656 785 1595 2117 2612 3110 3593 3874 4375 4840 5210 5549 5726 6229 6722 7096		1/2° 1/2° 1/2° 3/4° 1/2° 13/4° 13/4° 2° 3/4° 11/2° 11/2° 11/4° 11/2° 11/2° 11/2° 11/2° 11/2°						
			 B T	(Cor. y	npany or (	Mi El	<u>', I</u> nc.	
Subsc this 19_82	ribed and swor 23rd day _•		e me ,					
Matar	ussa K n	iller I for Midla	nd	. :				

County, Texas.



.