

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-160-1	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> WELL GAS <input checked="" type="checkbox"/> WELL OTHER- 2. Name of Operator Texaco Inc. 3. Address of Operator P.O. Box 728, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER B 851 FEET FROM THE North LINE AND 1825 FEET FROM THE East LINE, SECTION 20 TOWNSHIP 20-S RANGE 37-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3521 (GR.)	7. Unit Agreement Name 8. Farm or Lease Name New Mexico 'H' Stat Nct-2 9. Well No. 30 10. Field and Pool or Wildcat Lumont Yates Seven Rivers Queen 12. County Lea
---	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Perforate, Treat & Complete

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Total Depth 3600'. Plug back Total Depth 3568'. 8 5/8" OD 24# K-55 Csg. set @ 1100'. 5 1/2" OD 15.5# K-55 Csg. Set @ 3600'.

1. Perforate 5 1/2" Csg. w/2-JSPF @ 3361', 73', 77', 83', 89', 3400', 05', 10', 21', 30', 34', 40', 48', 57', 65', 69', 75', 86', & 3499'.
2. Spot 250 gals. 15% NEFE Acid over perfs. 3361'-3499'.
3. Set pkr. @ 3261', Acidize perfs 3361'-3499' w/1000 gals 75 Quality N2 & 15% NEFE Acid & 60 Ball Sealers. Flush w/75 quality N2 Foamed 2% KCI Water.
4. Well Completed as Shut-In Natural Gas, Waiting on Gas Connection, 3-4-82.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Mgr. DATE 3-8-82
APPROVED BY [Signature] TITLE Asst. Dist. Mgr. DATE 3-8-82
CONDITIONS OF APPROVAL, IF ANY:

MAR 15 1982