

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-27761</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name H.S. RECORD
8. Well No. 8
9. Pool name or Wildcat JALMAT TANSILL YATES SEVEN RIVERS
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3520.61 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator MERIDIAN OIL INC.	3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810	4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1400</u> Feet From The <u>EAST</u> Line Section <u>22</u> Township <u>22-S</u> Range <u>36-E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3520.61 GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTIFY NEW MEXICO OCD PRIOR TO STARTING WORK.

RUN 5 1/2" CASING SCRAPER TO 3300'.

SET A CIBP AT 3270', SET A 30SK CMT PLUG ON TOP OF THE CIBP UP TO 2990' TO COVER THE BASE OF THE SALT. CIRCULATE HOLE WITH 9 PPG BRINE UP TO 1780'.

SET A 10SK CMT PLUG FROM 1660' - 1760' TO COVER THE TOP OF THE SALT. CIRCULATE 9 PPG BRINE UP TO 510'.

SET A 55 SK CMT PLUG FROM SURFACE TO 510' TO COVER THE SURFACE CASING SHOE.

CUT OFF CASING 3 FT FROM SURFACE AND INSTALL P&A MONUMENT. CLEAR AND RESTORE LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maria L. Perez TITLE PROD. ASST. DATE 10-13-92
TYPE OR PRINT NAME MARIA L. PEREZ TELEPHONE NO. 915 688 6906

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

OCT 19 '92

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED OCT 22 1992
OIL CONSERVATION DIVISION
SANTA FE, NEW MEXICO