

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Morris R. Antweil		8. Farm or Lease Name Louie
3. Address of Operator P. O. Box 2010, Hobbs, NM 88241		9. Well No. 2
4. Location of Well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>860</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>20S</u> RANGE <u>38E</u> NMPM.		10. Field and Pool, or Wildcat West Nadine Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3583' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Perforate, treat and test</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drindard Perforations 6843' - 6886'.

Set CIBP at 6430' and capped with cement. Tested plug to 2000 psi. Perforated Blinbry with single shots at 5930', 5931', 5932', 5933', and 5934'. Acidized with 2000 gals 15% NEFE acid at 4 BPM and 3300 psi. ISIP 2200, 15 minsip 1700. Swabbed 1/2 BF in 4 hours with 70% cut. Fractured with 12,400 gals gelled water and 11,600# 20/40 sand. Sanded off. Put on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay TITLE Agent DATE 6/12/84

APPROVED BY Oil & Gas Inspector TITLE DATE JUN 13 1984

CONDITIONS OF APPROVAL, IF ANY: